



















Appendix D

Additional Site Investigations Summary Table

| Feature ID | Project Component | Investigation Date | Description | of Site | Feature Descriptions | Feature Sensitivity |
|------------|---|-----------------------|---|--|--|------------------------|
| R4.16-D | Road Buffer Turbine buffer Collection Line Buffer | June 20, 2013 | The watercourse flows throug stand that runs parallel Bog L another tributary and crosses becoming channelized as it rifields. No tile drain inputs we investigations. The watercourelatively flat and uniform lanbanks. Riparian buffer remair 30m on either side. As the wadownstream there are areas up to wide pools. Waterbody Name DFO Drain Classification | ine. then meets with under Lakeshore Rd.; uns through agricultural re noted at time of tree is located in a dscape with low sloping as consistent at approx. | This watercourse is defined historically as a channelized feature but has slowly naturalized. The watercourse is flat with some pooled areas. The water was slightly turbid, warm and had very low flow at time of investigation that at times could be an obstruction to fish passage. The banks were stable, and fairly vegetated. Substrate consists mostly of sand, with muck, clay and silt. Canopy cover is high consisting mostly of trees with some understory shrubs and grasses. Instream cover is high and consists of aquatic vegetation and some woody debris. School of young of year fish and tadpoles were observed during time of investigation. R4.16-D MWW(m): 2 MBD(m): 0.15 MBD(m): 0.5 | Moderate |
| | | Photos | Photograph 1. Site overview | ↑ A | | , |

| Feature ID | Project Component | Investigation Date | Description of Site | Feature Descriptions | Feature Sensitivity | |
|------------|---|-----------------------|--|--|------------------------|--|
| P4.51 | Road BufferTurbine 4 bufferCollection Line buffer | June 20, 2013 | This pond is located adjacent to agricultural fields. It is a natural depression that may have been altered by land owner. It is surrounded by scrub land that transitions into a deciduous forest stand. Its estimated size is 75m by 50m and its depth is unknown. | The pond is a semi dugout and as shown on aerial imagery, has a tributary that flows out of it towards the east and into Unknown tributary. Visible in-situ cover is low and consists of aquatic vegetation (cattails visible). Substrate unknown. | Non-REA | |
| Photos | | | Photograph 1. Site overview ↑ | | | |

| Feature ID | Project Component | Investigation Date | Description of Site | Feature Descriptions | Feature Sensitivity |
|------------|------------------------|-----------------------|--|---|------------------------|
| R3-C-1 | Collection Line Buffer | June 19, 2013 | This watercourse runs adjacent to a deciduous forest along Gordon Road, then crosses (south of Widder Road) and runs northwest through the same forest stand. It is channelized along the road then turns into a natural channel after crossing. After road crosses this water course is a natural meandering system with a moderately vegetated bank. The surrounding landscape is slightly sloped and has moderately dense canopy cover. Watercourse Name Decker Creek DFO Drain Classification F | The watercourse is a partially channelized feature that turns into a natural channel downstream. The watercourse is flat with some pooled areas and a natural riffle run sequence. The water was clear and had very slow flow at the time of investigation. Water was cool, with moderate water quality. The banks were slightly unstable and evidence of erosion was observed. Substrate consists mostly of clay, silt and sand with some cobble and a couple boulders. Canopy cover is high consisting mostly of trees and shrubs. Instream cover is moderate and consists of boulder, cobble, very little aquatic vegetation and some woody debris. Minnows were observed during investigation. R3-C-1 R3-C-1 R3-C-1 MWW(m): 0.22 MBW(m): 1 | Moderate |
| | | Photos | | ph 2. Site overview ↑ Photograph 3. View o | f canopy ↑ |

| Feature ID | Project Component | Investigation Date | Description of Site | | Feature Descriptions | Feature Sensitivity | |
|------------|---|-----------------------|--|--|---|------------------------|--|
| R4-J | Collection Line Buffer Road Buffer Turbine Buffer | July 12, 2013 | Watercourse flows through surrounded by corn and wh either side. It is south off of Jericho Road and crosses of Overland flow is noted to be and it has a gently sloped s Watercourse Name DFO Drain Classification | eat agricultural fields on f Highway 21 west of under Bruce Scott Road. e an input into this system | The watercourse is a historically channelized, permanent natural feature with a well-established natural riparian edge (~5-10m). The watercourse has a natural riffle/run sequence. The water had a consistent flow at time of investigation. The banks were slightly unstable, with evidence of erosion on left bank upstream. Substrate consists mostly of cobble, sand and gravel. Canopy cover is moderate consisting mostly of trees with some understory shrubs and herbaceous vegetation. Instream cover is low and consists of cobble and some woody debris (no instream vegetation). Woody debris creates 1.5m obstruction at the beginning of the site. R4-J | Moderate | |
| | Photograph 1. Site overview ↑ | | | | | | |