

**B6. Photographic Log of Pre-
construction Dewatering
Monitoring on April 28, 2014**

Appendix B6. Photographic Log of Pre-construction Dewatering Monitoring on April 28, 2014

Monitoring Location M1



Photograph 1. ↑
Pond and surrounding vegetation, facing west.



Photograph 2. ↑
Algae present in east end of pond.



Photograph 3. ↑
Manitoba Maple (*Acer negundo*)
trees surrounding pond.



Photograph 4. ↑
Location of culvert on east side of pond.

Appendix B6. Photographic Log of Pre-construction Dewatering Monitoring on April 28, 2014

Photograph 5. ↑
Location of culvert draining out into
watercourse east of pond.



Photograph 6. ↑
Mini-piezometer and staff gauge installed
at east end of pond, facing west.

Appendix B6. Photographic Log of Pre-construction Dewatering Monitoring on April 28, 2014

Monitoring Location R1



Photograph 7. ↑
Cultural meadows surrounding banks of pond,
facing east from monitoring location.



Photograph 8. ↑
Surrounding cultural meadows and Phragmites on
banks of pond, facing west from monitoring location.



Photograph 9. ↑
Red-osier thicket and cultural meadow
on north bank of pond.



Photograph 10. ↑
Possible muskrat den located on south
bank, across from monitoring location.

Appendix B6. Photographic Log of Pre-construction Dewatering Monitoring on April 28, 2014

Photograph 11. ↑
Mini-piezometer and staff gauge location.