WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-08
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-14_PUB-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8549130573 **Long:** -74.5112568359 **Datum:** WGS84
Soil Map Unit Name: Fonda mucky silty clay loam, Fo **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-14

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓_ Surface Water (A1)
- _✓_ High Water Table (A2)
- _✓_ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- _✓_ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- _✓_ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- _✓_ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- _✓_ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- _✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	12
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-14_PUB-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lemna minor*	100	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	100	x 1 =	100
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	100	(A)	100 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-14_PUB-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric. Soils were assumed to be hydric due to the presence of inundation, FACW and OBL vegetation species, and a definitive wetland boundary.

Hydrology Photos

Vegetation Photos

Photo of Sample Plot North

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-08
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-14_UPL-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** None **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8547585399 **Long:** -74.5112576338 **Datum:** WGS84
Soil Map Unit Name: Fonda mucky silty loam, Fo **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-14_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	80	Yes	FACU
2. *Fraxinus americana*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus americana*	20	Yes	FACU
2. *Acer saccharum*	20	Yes	FACU
3. *Tsuga canadensis*	10	Yes	FACU
4.			
5.			
6.			
7.			
	50	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Eurybia macrophylla*	45	Yes	UPL
2. *Geranium robertianum*	20	Yes	FACU
3. *Dryopteris carthusiana*	10	No	FACW
4. *Fraxinus americana*	10	No	FACU
5. *Toxicodendron radicans*	5	No	FAC
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	7	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	10	x 2 =	20
FAC species	5	x 3 =	15
FACU species	180	x 4 =	720
UPL species	45	x 5 =	225
Column Totals	240	(A)	980 (B)

Prevalence Index = B/A = 4.1

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-14_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/4	100					Silt Loam	
8 - 16	10YR 4/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-14_UPL-2
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.854666 **Long:** -74.51039 **Datum:** WGS84
Soil Map Unit Name: Fonda mucky silty clay loam, Fo **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-14_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	75	Yes	FACU
2. *Betula alleghaniensis*	30	Yes	FAC
3. *Ulmus americana*	15	No	FACW
4.			
5.			
6.			
7.			
	120	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Betula alleghaniensis*	25	Yes	FAC
2. *Carpinus caroliniana*	10	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	35	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1. *Carex pedunculata*	15	Yes	FAC
2. *Dryopteris intermedia*	3	No	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	18	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	80	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	15	x 2 =	30
FAC species	83	x 3 =	249
FACU species	75	x 4 =	300
UPL species	0	x 5 =	0
Column Totals	173	(A)	579 (B)
Prevalence Index = B/A =	3.3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-14_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 4/4	100					Silt Loam	
12 - 18	10YR 5/4	100					Silt Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-14_UPL-3
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Convex **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.854393 **Long:** -74.509286 **Datum:** WGS84
Soil Map Unit Name: Nunda channery silt loam, NuD **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-14_UPL-3

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Carya cordiformis*	60	Yes	FAC
2. *Acer saccharum*	20	Yes	FACU
3. *Tsuga canadensis*	10	No	FACU
4. *Carya ovata*	5	No	FACU
5. *Ulmus americana*	5	No	FACW
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Acer saccharum*	30	Yes	FACU
2. *Tsuga canadensis*	5	No	FACU
3.			
4.			
5.			
6.			
7.			
	35	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Carya cordiformis*	15	Yes	FAC
2. *Dryopteris intermedia*	5	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	20	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	10	Yes	FAC
2.			
3.			
4.			
	10	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: **4** (A)

Total Number of Dominant Species Across All Strata: **6** (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: **66.7** (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	5	x 2 =	10
FAC species	90	x 3 =	270
FACU species	70	x 4 =	280
UPL species	0	x 5 =	0
Column Totals	165	(A)	560 (B)

Prevalence Index = B/A = 3.4

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-14_UPL-3

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/3	100					Silt Loam	
6 - 12	10YR 3/3	100					Silt Loam	
12 - 18	10YR 4/3	95	10YR 4/6	5	C	M	Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-15_PUB-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hilltop **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.853052 **Long:** -74.506119 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuC **NWI classification:** PUS
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-15

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
_✓ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	15
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-15_PUB-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha latifolia*	10	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	10	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	10	x 1 =	10
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	10	(A)	10 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-15_PUB-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric. Soils were assumed to be hydric due to the presence of inundation, FACW and OBL vegetation species, and a definitive wetland boundary.

Hydrology Photos

Vegetation Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-15_UPL-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hilltop **Local relief (concave, convex, none):** Convex **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.852975 **Long:** -74.506291 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuC **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-15_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Trifolium pratense*	60	Yes	FACU
2. *Dactylis glomerata*	40	Yes	FACU
3. *Daucus carota*	30	No	UPL
4. *Thaspium barbinode*	20	No	UPL
5. *Lotus tenuis*	15	No	FACU
6. *Setaria pumila*	10	No	FAC
7. *Galium mollugo*	10	No	FACU
8.			
9.			
10.			
11.			
12.			
	185	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	125	x 4 =	500
UPL species	50	x 5 =	250
Column Totals	185	(A)	780 (B)
Prevalence Index = B/A =	4.2		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Pond embankment.

SOIL

Sampling Point: W-JMP-15_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 15	10YR 3/2	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-16_PEM-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.851724 **Long:** -74.50285 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam, IlA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-16

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (at least two secondary indicators).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-16_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tilia americana*	20	Yes	FACU
2. *Populus tremuloides*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	30	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Salix alba*	15	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	50	Yes	FACW
2. *Phragmites australis*	50	Yes	FACW
3. *Onoclea sensibilis*	20	No	FACW
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	120	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	60	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	135	x 2 =	270
FAC species	0	x 3 =	0
FACU species	30	x 4 =	120
UPL species	0	x 5 =	0
Column Totals	165	(A)	390 (B)
Prevalence Index = B/A =	2.4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-16_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	7.5YR 4/1	90	5YR 4/6	10	C	M	Silty Clay Loam	
12 - 18	10YR 4/1	80	2.5YR 4/6	20	C	M	Clay Loam	
18 - 20	10YR 5/1	60	7.5YR 5/8	40	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-16_PFO-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.852336 **Long:** -74.502468 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-16

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1	
Water Table Present?	Yes _✓_ No ____	Depth (inches):	5	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-16_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	50	Yes	FACU
2. *Acer saccharum*	40	Yes	FACU
3. *Tilia americana*	25	No	FACU
4. *Betula alleghaniensis*	15	No	FAC
5.			
6.			
7.			
	130	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carpinus caroliniana*	25	Yes	FAC
2. *Acer saccharum*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	35	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Toxicodendron radicans*	15	Yes	FAC
2. *Dryopteris intermedia*	15	Yes	FAC
3. *Impatiens capensis*	10	Yes	FACW
4. *Ranunculus repens*	10	Yes	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	50	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Parthenocissus quinquefolia*	10	Yes	FACU
2.			
3.			
4.			
	10	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	5	(A)
Total Number of Dominant Species Across All Strata:	9	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	55.6	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	10	x 2 =	20
FAC species	80	x 3 =	240
FACU species	135	x 4 =	540
UPL species	0	x 5 =	0
Column Totals	225	(A)	800 (B)
Prevalence Index = B/A =	3.6		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-16_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 2/1	98	7.5YR 4/6	2	C	M	Silty Clay Loam	
12 - 20	10YR 4/2	60	7.5YR 5/8	40	C	M	Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
_✓_ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
_✓_ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-16_UPL-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Convex **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8522869785 **Long:** -74.5025258588 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-16_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	60	Yes	FACU
2. *Acer saccharum*	35	Yes	FACU
3. *Fagus grandifolia*	15	No	FACU
4.			
5.			
6.			
7.			
	110	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Acer saccharum*	15	Yes	FACU
2. *Fagus grandifolia*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	25	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Toxicodendron radicans*	10	Yes	FAC
2. *Fagus grandifolia*	5	Yes	FACU
3. *Fraxinus americana*	5	Yes	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	20	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	10	Yes	FAC
2.			
3.			
4.			
	10	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	8	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	25	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	20	x 3 =	60
FACU species	145	x 4 =	580
UPL species	0	x 5 =	0
Column Totals	165	(A)	640 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-16_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 3	10YR 2/2	100					Silt Loam	
3 - 15	10YR 3/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-16_UPL-2
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8516348832 **Long:** -74.5029282248 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam, IlA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. Only one secondary indicator observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-16_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	50	Yes	FACW
2. *Setaria pumila*	50	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	50	x 2 =	100
FAC species	50	x 3 =	150
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	100	(A)	250 (B)
Prevalence Index = B/A =	2.5		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. Maintained road shoulder. A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-16_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/2	100					Clay Loam	
6 - 20	10YR 4/1	85	10YR 5/8	15	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-17_PFO-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.853082 **Long:** -74.509296 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-17

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
___ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓ Water-Stained Leaves (B9)
_✓ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-17_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	40	Yes	FACU
2. *Fagus grandifolia*	30	Yes	FACU
3. *Ulmus americana*	30	Yes	FACW
4. *Acer saccharum*	25	Yes	FACU
5.			
6.			
7.			
	125	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Tsuga canadensis*	15	Yes	FACU
2. *Ulmus americana*	10	Yes	FACW
3. *Fagus grandifolia*	5	No	FACU
4.			
5.			
6.			
7.			
	30	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	50	Yes	FACW
2. *Onoclea sensibilis*	25	Yes	FACW
3. *Parthenocissus quinquefolia*	15	No	FACU
4. *Solidago canadensis*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	5	(A)
Total Number of Dominant Species Across All Strata:	9	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	55.6	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	115	x 2 =	230
FAC species	15	x 3 =	45
FACU species	140	x 4 =	560
UPL species	0	x 5 =	0
Column Totals	270	(A)	835 (B)

Prevalence Index = B/A = 3.1

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-17_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 2/1	100					Clay Loam	
10 - 20	10YR 2/1	97	7.5YR 4/6	3	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-17_UPL-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** None **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8530737827 **Long:** -74.5093976599 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-17_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	60	Yes	FACU
2. *Tilia americana*	30	Yes	FACU
3. *Acer saccharum*	25	No	FACU
4. *Fagus grandifolia*	15	No	FACU
5.			
6.			
7.			
	130	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Tsuga canadensis*	15	Yes	FACU
2. *Acer saccharum*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	25	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Parthenocissus quinquefolia*	10	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	10	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: **0** (A)

Total Number of Dominant Species Across All Strata: **5** (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: **0** (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	165	x 4 =	660
UPL species	0	x 5 =	0
Column Totals	165	(A)	660 (B)

Prevalence Index = B/A = 4

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-17_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 7	10YR 2/2	100					Clay Loam	
7 - 10	10YR 3/2	80	5YR 4/6	3	C	M	Hemic Clay Loam	
7 - 10	10YR 4/3	17					Clay Loam	
10 - 16	10YR 4/3	80					Silt Loam	
10 - 16	10YR 3/2	20					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-18_PEM-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8613075757 **Long:** -74.5135815327 **Datum:** WGS84
Soil Map Unit Name: Churchville silty clay loam, ChB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-18

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-18_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	100	Yes	FACW
2. *Lythrum salicaria*	40	Yes	OBL
3. *Typha latifolia*	25	No	OBL
4. *Setaria pumila*	5	No	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	170	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	65	x 1 =	65
FACW species	100	x 2 =	200
FAC species	5	x 3 =	15
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	170	(A)	280 (B)
Prevalence Index = B/A =	1.6		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-18_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/1	100					Silty Clay Loam	
6 - 12	10YR 3/1	90	7.5YR 3/4	10	C	M	Silty Clay Loam	
12 - 20	10YR 2/1	85	5YR 3/4	15	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-09
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-18_UPL-1
Investigator(s): Jerry Peake, Carson Rowe, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8612435576 **Long:** -74.5136362935 **Datum:** WGS84
Soil Map Unit Name: Churchville silty clay loam, ChB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-18_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	60	Yes	UPL
2. *Setaria pumila*	40	Yes	FAC
3. *Echinochloa crus-galli*	20	No	FAC
4. *Lythrum salicaria*	20	No	OBL
5. *Cyperus strigosus*	10	No	FACW
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	150	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	20	x 1 =	20
FACW species	10	x 2 =	20
FAC species	60	x 3 =	180
FACU species	0	x 4 =	0
UPL species	60	x 5 =	300
Column Totals	150	(A)	520 (B)
Prevalence Index = B/A =	3.5		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-18_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/1	100					Silty Clay Loam	
8 - 15	10YR 3/1	95	7.5YR 3/4	5	C	M/PL		
15 - 18	2.5Y 4/2	60	10YR 4/6	15	C	M	Clay Loam	
15 - 18	10YR 3/1	25					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met. Soil significantly disturbed as a result of tilling. Soil disturbed, although not significantly enough to obscure hydric soil indicators, as a result of historical filling or grading.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgoe=mery **Sampling Date:** 2021-Sept-13
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-19_PFO-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Valley **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8401503123 **Long:** -74.4919382712 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD **NWI classification:** R2UB
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-19

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓ Surface Water (A1)
- ___ High Water Table (A2)
- _✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- _✓ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- _✓ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- _✓ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-19_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	50	Yes	FACU
2. *Fraxinus americana*	35	Yes	FACU
3. *Fraxinus pennsylvanica*	30	Yes	FACW
4. *Betula alleghaniensis*	20	No	FAC
5. *Ulmus americana*	10	No	FACW
6.			
7.			
	145	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carpinus caroliniana*	25	Yes	FAC
2. *Tsuga canadensis*	10	Yes	FACU
3. *Ulmus americana*	10	Yes	FACW
4.			
5.			
6.			
7.			
	45	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Toxicodendron radicans*	15	Yes	FAC
2. *Geum canadense*	5	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	20	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: **5** (A)

Total Number of Dominant Species Across All Strata: **8** (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: **62.5** (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	50	x 2 =	100
FAC species	65	x 3 =	195
FACU species	95	x 4 =	380
UPL species	0	x 5 =	0
Column Totals	210	(A)	675 (B)

Prevalence Index = B/A = 3.2

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-19_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 2/1	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
_✓_ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** , **Sampling Date:** 2021-Sept-13
Applicant/Owner: SunEast **State:** **Sampling Point:** W-JMP-19_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Slope **Slope (%):** 5 to 10
Subregion (LRR or MLRA): LRR L **Lat:** 42.8401176297 **Long:** -74.4919898158 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-19_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	80	Yes	FACU
2. *Carya ovata*	15	No	FACU
3. *Acer saccharum*	15	No	FACU
4.			
5.			
6.			
7.			
	110	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Tsuga canadensis*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	0	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	125	x 4 =	500
UPL species	0	x 5 =	0
Column Totals	125	(A)	500 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-19_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 5	10YR 3/3	100					Silt Loam	
5 - 20	10YR 3/4	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-13
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-20_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8411358206 **Long:** -74.4918361899 **Datum:** WGS84
Soil Map Unit Name: Churchville silty clay loam, ChB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-20

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	2
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-20_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus amomum*	15	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Symphyotrichum lanceolatum*	80	Yes	FACW
2. *Euthamia graminifolia*	40	Yes	FAC
3. *Alisma plantago-aquatica*	20	No	OBL
4. *Galium mollugo*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	150	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	20	x 1 =	20
FACW species	95	x 2 =	190
FAC species	40	x 3 =	120
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	165	(A)	370 (B)
Prevalence Index = B/A =	2.2		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-20_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/1	97	5YR 4/6	3	C	M/PL	Clay Loam	
12 - 20	10YR 3/2	95	7.5YR 4/6	5	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Sept-13
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-20_PSS-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8413027992 **Long:** -74.4918426364 **Datum:** WGS84
Soil Map Unit Name: Churchville silty clay loam, ChB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-20

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	3	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-20_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Quercus rubra*	40	Yes	FACU
2. *Fraxinus americana*	25	Yes	FACU
3. *Acer saccharum*	20	Yes	FACU
4. *Malus sp.*	10	No	NI
5.			
6.			
7.			
	95	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus amomum*	60	Yes	FACW
2. *Rhamnus cathartica*	30	Yes	FAC
3. *Salix alba*	15	No	FACW
4. *Lonicera morrowii*	10	No	FACU
5.			
6.			
7.			
	115	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	40	Yes	FACU
2. *Onoclea sensibilis*	40	Yes	FACW
3. *Euthamia graminifolia*	25	No	FAC
4. *Impatiens capensis*	20	No	FACW
5. *Symphyotrichum novae-angliae*	15	No	FACW
6. *Symphyotrichum puniceum*	5	No	OBL
7.			
8.			
9.			
10.			
11.			
12.			
	145	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	8	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	150	x 2 =	300
FAC species	70	x 3 =	210
FACU species	135	x 4 =	540
UPL species	0	x 5 =	0
Column Totals	360	(A)	1055 (B)

Prevalence Index = B/A = 2.9

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-20_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 5	10YR 3/1	100					Silty Clay Loam	
5 - 13	10YR 3/2	95	5YR 3/4	5	C	M	Silty Clay Loam	
13 - 20	10YR 4/2	85	2.5YR 4/8	10	C	M	Silty Clay Loam	
13 - 20			2.5YR 3/6	5	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Sept-13
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-20_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8412102155 **Long:** -74.4916981408 **Datum:** WGS84
Soil Map Unit Name: Churchville silty clay loam, ChB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-20_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Taraxacum officinale*	50	Yes	FACU
2. *Galium mollugo*	30	Yes	FACU
3. *Trifolium pratense*	20	No	FACU
4. *Dactylis glomerata*	20	No	FACU
5. *Trifolium repens*	10	No	FACU
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	130	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	130	x 4 =	520
UPL species	0	x 5 =	0
Column Totals	130	(A)	520 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Fallow field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-20_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/2	100					Clay Loam	
8 - 20	10YR 4/2	75	7.5YR 4/6	25	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-21_PFO-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8417838982 **Long:** -74.4980779507 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-21

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (at least two secondary indicators).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-21_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	40	Yes	FACU
2. *Fraxinus americana*	30	Yes	FACU
3. *Acer saccharum*	15	No	FACU
4. *Carya ovata*	10	No	FACU
5.			
6.			
7.			
	95	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rhamnus cathartica*	20	Yes	FAC
2. *Fraxinus americana*	10	Yes	FACU
3. *Acer saccharum*	10	Yes	FACU
4. *Rosa multiflora*	10	Yes	FACU
5.			
6.			
7.			
	50	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dryopteris carthusiana*	40	Yes	FACW
2. *Impatiens capensis*	30	Yes	FACW
3. *Onoclea sensibilis*	30	Yes	FACW
4. *Euthamia graminifolia*	20	No	FAC
5. *Amphicarpaea bracteata*	10	No	FAC
6. *Symphyotrichum lanceolatum*	10	No	FACW
7. *Solidago gigantea*	10	No	FACW
8.			
9.			
10.			
11.			
12.			
	150	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	5	(A)
Total Number of Dominant Species Across All Strata:	10	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	120	x 2 =	240
FAC species	65	x 3 =	195
FACU species	125	x 4 =	500
UPL species	0	x 5 =	0
Column Totals	310	(A)	935 (B)
Prevalence Index = B/A =	3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-21_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/1	95	10YR 3/6	5	C	M	Silty Clay Loam	
8 - 20	10YR 4/4	85	5YR 4/6	15	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-21_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Saddle **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8417189072 **Long:** -74.4981645791 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-21_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	40	Yes	FACU
2. *Acer saccharum*	30	Yes	FACU
3. *Ulmus americana*	20	No	FACW
4. *Populus grandidentata*	20	No	FACU
5. *Tilia americana*	10	No	FACU
6.			
7.			
	120	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Acer saccharum*	15	Yes	FACU
2. *Carya ovata*	10	Yes	FACU
3. *Ulmus americana*	5	No	FACW
4.			
5.			
6.			
7.			
	30	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dryopteris carthusiana*	15	Yes	FACW
2. *Fraxinus americana*	5	Yes	FACU
3. *Geum canadense*	3	No	FAC
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	23	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 16.7 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	40	x 2 =	80
FAC species	3	x 3 =	9
FACU species	130	x 4 =	520
UPL species	0	x 5 =	0
Column Totals	173	(A)	609 (B)

Prevalence Index = B/A = 3.5

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-21_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 3/4	100					Silt Loam	
10 - 18	10YR 4/6	100					Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-22_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8386531266 **Long:** -74.4951699372 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-22

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓ Surface Water (A1)
- _✓ High Water Table (A2)
- _✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- _✓ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- _✓ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	3
Water Table Present?	Yes _✓_ No ____	Depth (inches):	9
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	13

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-22_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	25	Yes	FACU
2. *Fraxinus americana*	15	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	40	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus racemosa*	40	Yes	FAC
2. *Cornus amomum*	15	Yes	FACW
3. *Salix bebbiana*	10	No	FACW
4.			
5.			
6.			
7.			
	65	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Eleocharis mamillata*	40	Yes	OBL
2. *Cyperus rotundus*	25	Yes	FACU
3. *Ludwigia palustris*	15	No	OBL
4. *Onoclea sensibilis*	10	No	FACW
5. *Wolffia columbiana*	10	No	OBL
6. *Barbarea vulgaris*	5	No	FAC
7.			
8.			
9.			
10.			
11.			
12.			
	105	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	65	x 1 =	65
FACW species	35	x 2 =	70
FAC species	45	x 3 =	135
FACU species	65	x 4 =	260
UPL species	0	x 5 =	0
Column Totals	210	(A)	530 (B)
Prevalence Index = B/A =	2.5		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-22_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 4/2	90	5YR 3/4	10	C	M	Clay Loam	
10 - 20	10YR 3/2	80	5YR 5/8	20	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. Soil significantly disturbed as a result of tilling.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-22_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8386407488 **Long:** -74.4952733423 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-22_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	30	Yes	FACU
2. *Salix bebbiana*	10	Yes	FACW
3. *Fraxinus americana*	10	Yes	FACU
4.			
5.			
6.			
7.			
	50	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus racemosa*	25	Yes	FAC
2. *Cornus amomum*	15	Yes	FACW
3. *Acer saccharum*	10	No	FACU
4. *Fraxinus americana*	10	No	FACU
5.			
6.			
7.			
	60	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	40	Yes	UPL
2. *Solidago canadensis*	20	Yes	FACU
3. *Parthenocissus quinquefolia*	10	No	FACU
4. *Cyperus rotundus*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	80	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 3 (A)

Total Number of Dominant Species Across All Strata: 7 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 42.9 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	25	x 2 =	50
FAC species	25	x 3 =	75
FACU species	100	x 4 =	400
UPL species	40	x 5 =	200
Column Totals	190	(A)	725 (B)

Prevalence Index = B/A = 3.8

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-22_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 9	10YR 3/4	100					Clay Loam	
9 - 16	10YR 3/4	25	5YR 3/4	20	C	M	Clay Loam	
9 - 16	10YR 4/2	55					Clay Loam	
16 - 20	10YR 4/4	95	7.5YR 4/6	5	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot
North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-23_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8469583821 **Long:** -74.4887195064 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-23

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	10	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-23_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	60	Yes	FACU
2. *Galium mollugo*	50	Yes	FACU
3. *Typha angustifolia*	40	Yes	OBL
4. *Onoclea sensibilis*	30	No	FACW
5. *Symphyotrichum lanceolatum*	20	No	FACW
6. *Equisetum arvense*	20	No	FAC
7. *Symphyotrichum novae-angliae*	10	No	FACW
8. *Centaurea jacea*	10	No	FACU
9. *Ranunculus acris*	5	No	FAC
10.			
11.			
12.			
	245	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	25	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	40	x 1 =	40
FACW species	60	x 2 =	120
FAC species	25	x 3 =	75
FACU species	135	x 4 =	540
UPL species	0	x 5 =	0
Column Totals	260	(A)	775 (B)
Prevalence Index = B/A =	3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

__✓__ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes __✓__ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-23_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/2	90	2.5YR 3/6	5	C	M/PL	Silty Clay Loam	
12 - 20	10YR 3/2	80	7.5YR 5/8	20				

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-23_PUB-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.846644 **Long:** -74.488712 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** PUS
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-23

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓_ Surface Water (A1)
- _✓_ High Water Table (A2)
- _✓_ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- _✓_ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- _✓_ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- _✓_ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- _✓_ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- _✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	15
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-23_PUB-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Myriophyllum spicatum*	75	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	75	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	75	x 1 =	75
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	75	(A)	75 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-23_PUB-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric. Soils were assumed to be hydric due to the presence of inundation, FACW and OBL vegetation species, and a definitive wetland boundary.

Hydrology Photos

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-23_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8470274436 **Long:** -74.4887698738 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-23_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	80	Yes	FACU
2. *Centaurea jacea*	60	Yes	FACU
3. *Asclepias syriaca*	10	No	UPL
4. *Symphyotrichum novae-angliae*	8	No	FACW
5. *Fragaria vesca*	5	No	UPL
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	163	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	8	x 2 =	16
FAC species	0	x 3 =	0
FACU species	155	x 4 =	620
UPL species	15	x 5 =	75
Column Totals	178	(A)	711 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-23_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/2	100					Clay Loam	
12 - 16	10YR 3/2	95	7.5YR 4/6	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-14
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-23_UPL-2
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Convex **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8466074968 **Long:** -74.4888833995 **Datum:** WGS84
Soil Map Unit Name: Burdett channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-23_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rhamnus cathartica*	40	Yes	FAC
2. *Elaeagnus umbellata*	10	No	NI
3. *Lonicera morrowii*	10	No	FACU
4. *Cornus amomum*	5	No	FACW
5.			
6.			
7.			
	65	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	85	Yes	FACU
2. *Phalaris arundinacea*	50	Yes	FACW
3. *Centaurea jacea*	10	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	145	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	66.7	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	55	x 2 =	110
FAC species	40	x 3 =	120
FACU species	105	x 4 =	420
UPL species	0	x 5 =	0
Column Totals	200	(A)	650 (B)

Prevalence Index = B/A = 3.3

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-JMP-23_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 18	10YR 3/3	95	7.5YR 5/6	5	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-24_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8445281658 **Long:** -74.4888890662 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-24

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes _✓_ No ____	Depth (inches):	4
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	4

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-24_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lythrum salicaria*	85	Yes	OBL
2. *Symphyotrichum lanceolatum*	25	Yes	FACW
3. *Juncus tenuis*	25	Yes	FAC
4. *Impatiens capensis*	20	No	FACW
5. *Euthamia graminifolia*	20	No	FAC
6. *Plantago rugelii*	10	No	FAC
7. *Melilotus indicus*	10	No	FACU
8.			
9.			
10.			
11.			
12.			
	195	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	85	x 1 =	85
FACW species	45	x 2 =	90
FAC species	55	x 3 =	165
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	195	(A)	380 (B)
Prevalence Index = B/A =	1.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-24_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 2/2	98	10YR 4/6	2	C	M	Silty Clay Loam	
6 - 15	10YR 5/3	80	7.5YR 4/6	20	C	M	Silty Clay Loam	Some gravel within line 2, suspected fill

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-24_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Terrace **Local relief (concave, convex, none):** None **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8445447644 **Long:** -74.4890736766 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-24_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lolium perenne*	100	Yes	FACU
2. *Euthamia graminifolia*	20	No	FAC
3. *Centaurea jacea*	10	No	FACU
4. *Galium mollugo*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	140	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	20	x 3 =	60
FACU species	120	x 4 =	480
UPL species	0	x 5 =	0
Column Totals	140	(A)	540 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-24_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 9	10YR 3/2	100					Silty Clay Loam	
9 - 20	10YR 3/3	95	2.5YR 4/6	5	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-25_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.859489 **Long:** -74.518796 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam,IIA **NWI classification:** R2UB
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-25

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	18	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-25_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	100	Yes	FACW
2. *Symphyotrichum puniceum*	20	No	OBL
3. *Lythrum salicaria*	15	No	OBL
4. *Typha latifolia*	5	No	OBL
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	140	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	40	x 1 =	40
FACW species	100	x 2 =	200
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	140	(A)	240 (B)
Prevalence Index = B/A =	1.7		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-25_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 2/2	100					Silt Loam	
4 - 12	10YR 3/1	90	10YR 4/6	10	C	M	Silty Clay Loam	
12 - 20	10YR 3/1	85	5YR 4/6	15	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-25_PSS-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8590702685 **Long:** -74.5168342797 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam, IlA **NWI classification:** R2UB
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-25

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes _✓_ No ____	Depth (inches):	10
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (at least two secondary indicators).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-25_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus amomum*	40	Yes	FACW
2. *Salix alba*	30	Yes	FACW
3. *Viburnum lentago*	10	No	FAC
4.			
5.			
6.			
7.			
	80	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	50	Yes	FACW
2. *Solidago canadensis*	30	Yes	FACU
3. *Amphicarpaea bracteata*	20	No	FAC
4. *Onoclea sensibilis*	20	No	FACW
5. *Symphyotrichum lanceolatum*	10	No	FACW
6. *Poa palustris*	10	No	FACW
7.			
8.			
9.			
10.			
11.			
12.			
	140	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	75	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	160	x 2 =	320
FAC species	30	x 3 =	90
FACU species	30	x 4 =	120
UPL species	0	x 5 =	0
Column Totals	220	(A)	530 (B)

Prevalence Index = B/A = 2.4

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-25_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/1	100					Silty Clay Loam	
8 - 20	10YR 3/1	97	10YR 4/6	3	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-25_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8591717432 **Long:** -74.518915446 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam, IlA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-25_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dactylis glomerata*	100	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	100	x 4 =	400
UPL species	0	x 5 =	0
Column Totals	100	(A)	400 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-25_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/3	100					Silt Loam	
8 - 20	10YR 4/3	90	7.5YR 4/6	10	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Vegetation Photos

Soil Photos

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-15
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-25_UPL-2
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.859162 **Long:** -74.516828 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam,IIA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓ Surface Water (A1)
- _✓ High Water Table (A2)
- _✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- ___ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
Hydrology is influenced by heavy rain prior to data plot collection.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-25_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dactylis glomerata*	80	Yes	FACU
2. *Trifolium pratense*	25	Yes	FACU
3. *Plantago major*	15	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	120	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	120	x 4 =	480
UPL species	0	x 5 =	0
Column Totals	120	(A)	480 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-25_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 9	10YR 3/3	100					Silty Clay Loam	
9 - 15								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. Refusal due to coarse fragments.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-26_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8589577498 **Long:** -74.5202189177 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam, IlA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No _✓_ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-26

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation. Circumstances are not normal due to agricultural activities. Heavy rain storms day/night prior to data plot collection.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓_ Surface Water (A1)
- _✓_ High Water Table (A2)
- _✓_ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- _✓_ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- _✓_ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- _✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-26_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer negundo*	20	Yes	FAC
2. *Acer saccharinum*	15	Yes	FACW
3.			
4.			
5.			
6.			
7.			
	35	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus amomum*	15	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lysimachia nummularia*	80	Yes	FACW
2. *Phalaris arundinacea*	60	Yes	FACW
3. *Lythrum salicaria*	30	No	OBL
4. *Impatiens capensis*	25	No	FACW
5. *Symphyotrichum lanceolatum*	15	No	FACW
6. *Solidago canadensis*	10	No	FACU
7. *Galium mollugo*	10	No	FACU
8. *Poa palustris*	10	No	FACW
9.			
10.			
11.			
12.			
	240	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	6	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	30	x 1 =	30
FACW species	220	x 2 =	440
FAC species	35	x 3 =	105
FACU species	20	x 4 =	80
UPL species	0	x 5 =	0
Column Totals	305	(A)	655 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-26_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 3/2	100					Silty Clay Loam	
4 - 10	10YR 4/1	95	7.5YR 3/4	5	C	M	Silty Clay Loam	
10 - 20	10YR 4/3	75	7.5YR 4/6	25	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
_✓_ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-26_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8588095524 **Long:** -74.5201618368 **Datum:** WGS84
Soil Map Unit Name: Ilion silt loam,IIA **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation. Circumstances are not normal due to agricultural activities. Heavy rain day/night prior to data plot collection.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ✓ No ____	Depth (inches):	1
Water Table Present?	Yes ✓ No ____	Depth (inches):	16
Saturation Present? (includes capillary fringe)	Yes ✓ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes ____ No ✓

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. Soil is episaturated.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-26_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dactylis glomerata*	100	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	100	x 4 =	400
UPL species	0	x 5 =	0
Column Totals	100	(A)	400 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-26_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/2	95	7.5YR 3/4	5	C	M	Clay Loam	
8 - 18	10YR 4/1	60	7.5YR 4/6	40	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
_✓_ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-27_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.859705 **Long:** -74.516406 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ✓ No ____**
Wetland Hydrology Present?	Yes ✓ No ____	**If yes, optional Wetland Site ID:**	W-JMP-27

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. ATV/ORV impacts observed. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- ✓ Surface Water (A1)
- ✓ High Water Table (A2)
- ✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ✓ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- ✓ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ✓ No ____	Depth (inches):	2	
Water Table Present?	Yes ✓ No ____	Depth (inches):	8	**Wetland Hydrology Present?** Yes ✓ No ____
Saturation Present? (includes capillary fringe)	Yes ✓ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-27_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Quercus rubra*	20	Yes	FACU
2. *Tilia americana*	15	Yes	FACU
3. *Carya ovata*	10	No	FACU
4. *Populus tremuloides*	10	No	FACU
5.			
6.			
7.			
	55	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Populus tremuloides*	5	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	5	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Persicaria sagittata*	50	Yes	OBL
2. *Leersia oryzoides*	40	Yes	OBL
3. *Carex pedunculata*	25	No	FAC
4. *Phalaris arundinacea*	20	No	FACW
5. *Poa palustris*	10	No	FACW
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	145	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	40	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	90	x 1 =	90
FACW species	30	x 2 =	60
FAC species	25	x 3 =	75
FACU species	60	x 4 =	240
UPL species	0	x 5 =	0
Column Totals	205	(A)	465 (B)
Prevalence Index = B/A =	2.3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-27_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 3/2	95	10YR 4/6	5	C	M	Silty Clay Loam	
4 - 15	10YR 4/1	85	7.5YR 4/4	15	C	M	Clay Loam	
15 - 20	10YR 3/2	40	7.5YR 4/4	20	C	M	Clay Loam	
15 - 20	10YR 3/1	40					Clay Loam	
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
_✓_ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-27_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.859619 **Long:** -74.516526 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Circumstances are not normal due to mowing of vegetation. Heavy precipitation day/night prior to data plot collection.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-27_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Quercus rubra*	15	Yes	FACU
2. *Populus tremuloides*	10	Yes	FACU
3. *Tilia americana*	10	Yes	FACU
4.			
5.			
6.			
7.			
	35	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1. *Dactylis glomerata*	80	Yes	FACU
2. *Taraxacum officinale*	15	No	FACU
3. *Trifolium repens*	15	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	110	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	145	x 4 =	580
UPL species	0	x 5 =	0
Column Totals	145	(A)	580 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-27_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 3	10YR 4/2	100					Silt Loam	
3 - 15	10YR 4/2	95	10YR 4/6	5	C	M	Silty Clay Loam	
15 - 20	10YR 4/3	85	10YR 5/8	10	C	M	Silty Clay Loam	
15 - 20			5YR 4/6	5	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-28_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Channel **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8562141583 **Long:** -74.5120772527 **Datum:** WGS84
Soil Map Unit Name: Fonda mucky silty clay loam, Fo **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ✓ No ____**
Wetland Hydrology Present?	Yes ✓ No ____	**If yes, optional Wetland Site ID:**	W-JMP-28

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Heavy precipitation day/night prior to data plot collection.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- ✓ Surface Water (A1)
- ✓ High Water Table (A2)
- ✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ✓ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Stunted or Stressed Plants (D1)
- ✓ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- ✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ✓ No ____	Depth (inches):	2
Water Table Present?	Yes ✓ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes ✓ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes ✓ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-28_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	100	Yes	FACW
2. *Typha latifolia*	30	No	OBL
3. *Lythrum salicaria*	10	No	OBL
4. *Solidago canadensis*	10	No	FACU
5. *Impatiens capensis*	5	No	FACW
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	155	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	40	x 1 =	40
FACW species	105	x 2 =	210
FAC species	0	x 3 =	0
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	155	(A)	290 (B)
Prevalence Index = B/A =	1.9		

Hydrophytic Vegetation Indicators:

_✓_ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-28_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/1	95	5YR 3/4	5	C	M	Silty Clay Loam	
8 - 20	10YR 3/1	100					Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-28_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8562156011 **Long:** -74.51207831 **Datum:** WGS84
Soil Map Unit Name: Fonda mucky silty clay loam, Fo **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ___, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ___, Soil ___, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-28_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	100	Yes	FACU
2. *Parthenocissus quinquefolia*	10	No	FACU
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	110	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	110	x 4 =	440
UPL species	0	x 5 =	0
Column Totals	110	(A)	440 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Fallow field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-28_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 3/2	100					Silty Clay Loam	
10 - 20	10YR 4/2	90	7.5YR 5/8	10	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
_✓_ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-29_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8544896026 **Long:** -74.5221218341 **Datum:** WGS84
Soil Map Unit Name: Fredon silt loam, Fr **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No _✓_ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-29

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Heavy precipitation day/night prior to data plot collection. Data plot collected in regularly tilled field.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓ Surface Water (A1)
- _✓ High Water Table (A2)
- _✓ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- _✓ Stunted or Stressed Plants (D1)
- _✓ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- _✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	2	
Water Table Present?	Yes _✓_ No ____	Depth (inches):	12	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-29_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	60	Yes	FACW
2. *Cyperus erythrorhizos*	30	Yes	OBL
3. *Plantago major*	15	No	FACU
4. *Acalypha virginica*	5	No	FACU
5. *Barbarea vulgaris*	5	No	FAC
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	115	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	30	x 1 =	30
FACW species	60	x 2 =	120
FAC species	5	x 3 =	15
FACU species	20	x 4 =	80
UPL species	0	x 5 =	0
Column Totals	115	(A)	245 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-JMP-29_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 3/1	97	7.5YR 4/4	3	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
✓ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met. Soil significantly disturbed as a result of tilling.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-29_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8547103731 **Long:** -74.5220850046 **Datum:** WGS84
Soil Map Unit Name: Burdette channery silt loam, BuB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Heavy precipitation day/night prior to data plot collection.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-29_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	70	Yes	UPL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	70	x 5 =	350
Column Totals	70	(A)	350 (B)
Prevalence Index = B/A =	5		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-29_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 16	10YR 3/2	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. Soil significantly disturbed as a result of tilling.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-30_PEM-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8573130771 **Long:** -74.5210326346 **Datum:** WGS84
Soil Map Unit Name: Madalin silty clay loam, Ma **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No _✓_ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil _✓_, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-JMP-30

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Heavy precipitation day/night prior to data plot collection .

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

- _✓_ Surface Water (A1)
- _✓_ High Water Table (A2)
- _✓_ Saturation (A3)
- ___ Water Marks (B1)
- ___ Sediment Deposits (B2)
- ___ Drift Deposits (B3)
- ___ Algal Mat or Crust (B4)
- ___ Iron Deposits (B5)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Sparsely Vegetated Concave Surface (B8)
- ___ Water-Stained Leaves (B9)
- ___ Aquatic Fauna (B13)
- ___ Marl Deposits (B15)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres on Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

- ___ Surface Soil Cracks (B6)
- ___ Drainage Patterns (B10)
- ___ Moss Trim Lines (B16)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- _✓_ Stunted or Stressed Plants (D1)
- _✓_ Geomorphic Position (D2)
- ___ Shallow Aquitard (D3)
- ___ Microtopographic Relief (D4)
- _✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes _✓_ No ____	Depth (inches):	5
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-30_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Cyperus erythrorhizos*	50	Yes	OBL
2. *Carex pedunculata*	30	Yes	FAC
3. *Phalaris arundinacea*	20	No	FACW
4. *Ranunculus repens*	10	No	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	110	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	50	x 1 =	50
FACW species	20	x 2 =	40
FAC species	40	x 3 =	120
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	110	(A)	210 (B)
Prevalence Index = B/A =	1.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-JMP-30_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 16	10YR 2/1	100					Silty Clay Loam	
16 - 20	10YR 2/1	95	7.5R 5/8	5	C	M	Silty Clay	
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
_✓_ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Soil significantly disturbed as a result of tilling. Soil disturbed, although not significantly enough to obscure hydric soil indicators, as a result of historical filling or grading.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-30_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.857353 **Long:** -74.52095 **Datum:** WGS84
Soil Map Unit Name: Madalin silty clay loam, Ma **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities. Heavy precipitation day/night prior to data plot collection .

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-30_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	75	Yes	UPL
2. *Ranunculus repens*	10	No	FAC
3. *Cyperus rotundus*	5	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	5	x 4 =	20
UPL species	75	x 5 =	375
Column Totals	90	(A)	425 (B)

Prevalence Index = B/A = 4.7

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-30_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 16	10YR 3/1	100					Clay Loam	
16 - 20	10YR 2/1	85	5YR 4/6	15	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil significantly disturbed as a result of tilling.

Vegetation Photos

Soil Photos

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-17
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-31_UPL-1
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** None **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8529008167 **Long:** -74.5141566474 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, DaB **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-31_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Holcus lanatus*	90	Yes	FACU
2. *Rumex crispus*	20	No	FAC
3. *Echinochloa crus-galli*	10	No	FAC
4. *Persicaria hydropiper*	5	No	OBL
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	125	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	0	x 2 =	0
FAC species	30	x 3 =	90
FACU species	90	x 4 =	360
UPL species	0	x 5 =	0
Column Totals	125	(A)	455 (B)
Prevalence Index = B/A =	3.6		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-31_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 3/2	100					Silty Clay Loam	
10 - 16	10YR 4/2	60	10YR 4/6	10	C	M	Silty Clay Loam	
10 - 16	10YR 3/2	30					Silty Clay Loam	
16 - 20	10YR 4/3	90	10YR 5/6	10	C	M	Clay Loam	
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-17
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-JMP-31_UPL-2
Investigator(s): Jerry Peake, Steve Spotts, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8533657271 **Long:** -74.5153211901 **Datum:** WGS84
Soil Map Unit Name: Madalin silty clay loam, Ma **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation. Circumstances are not normal due to agricultural activities. Heavy precipitation 2 days prior to data plot collection .

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-JMP-31_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Holcus lanatus*	90	Yes	FACU
2. *Trifolium repens*	30	Yes	FACU
3. *Echinochloa crus-galli*	15	No	FAC
4. *Oxalis dillenii*	10	No	FACU
5. *Eragrostis spectabilis*	5	No	UPL
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	150	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	15	x 3 =	45
FACU species	130	x 4 =	520
UPL species	5	x 5 =	25
Column Totals	150	(A)	590 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field. No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-JMP-31_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 15	10YR 3/2	100					Silty Clay Loam	
15 - 20	10YR 4/2	85	7.5YR 4/6	15	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Vegetation Photos

Soil Photos

Photo of Sample Plot East

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-01_PSS-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flood Plain **Local relief (concave, convex, none):** Concave **Slope (%):** 5 to 10
Subregion (LRR or MLRA): LRR R **Lat:** 42.89196262 **Long:** -74.49732032 **Datum:** WGS84
Soil Map Unit Name: RLF - Rock outcrop-Farmington association, very steep **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-01

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-01_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Carya ovata*	5	Yes	FACU
2. *Acer saccharum*	2	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	7	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carpinus caroliniana*	15	Yes	FAC
2. *Tilia americana*	5	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	20	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	30	Yes	FACW
2. *Athyrium angustum*	5	No	FAC
3. *Urtica dioica*	5	No	FAC
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	40	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	40	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	30	x 2 =	60
FAC species	25	x 3 =	75
FACU species	12	x 4 =	48
UPL species	0	x 5 =	0
Column Totals	67	(A)	183 (B)

Prevalence Index = B/A = 2.7

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-01_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/2	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-01_UPL-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Convex **Slope (%):** 15 to 20
Subregion (LRR or MLRA): LRR R **Lat:** 42.89186612 **Long:** -74.49735634 **Datum:** WGS84
Soil Map Unit Name: RLF - Rock outcrop-Farmington association, very steep **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-01_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	5	Yes	FACU
2. *Fraxinus americana*	5	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus americana*	60	Yes	FACU
2. *Fagus grandifolia*	10	No	FACU
3. *Acer saccharum*	5	No	FACU
4. *Hamamelis virginiana*	5	No	FACU
5.			
6.			
7.			
	80	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Athyrium angustum*	5	Yes	FAC
2. *Urtica dioica*	5	Yes	FAC
3. *Trillium cernuum*	5	Yes	FAC
4. *Tiarella cordifolia*	5	Yes	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	20	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	7	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	42.9	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	15	x 3 =	45
FACU species	95	x 4 =	380
UPL species	0	x 5 =	0
Column Totals	110	(A)	425 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-01_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/2	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-02_PEM-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Back slope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR R **Lat:** 42.89005792 **Long:** -74.49627963 **Datum:** WGS84
Soil Map Unit Name: NeC - Nellis loam, 8 to 15 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-02

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-02_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rosa multiflora*	10	Yes	FACU
2. *Fraxinus americana*	5	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	30	Yes	FACW
2. *Symplocarpus foetidus*	5	No	OBL
3. *Asteracae*	5	No	NI
4. *Persicaria virginiana*	5	No	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	45	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	5	Yes	FAC
2.			
3.			
4.			
	5	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	30	x 2 =	60
FAC species	10	x 3 =	30
FACU species	15	x 4 =	60
UPL species	0	x 5 =	0
Column Totals	60	(A)	155 (B)

Prevalence Index = B/A = 2.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-02_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/2	90	10YR 5/6	5	C	M	Silty Clay Loam	
0 - 8	10YR 3/2	90	10YR 4/2	5	D	M	Silty Clay Loam	
8 - 14	10YR 5/2	60					Sand	
8 - 14	10YR 5/3	40					Sand	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
_✓_ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-16
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-02_UPL-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR R **Lat:** 42.890138 **Long:** -74.49636 **Datum:** WGS84
Soil Map Unit Name: NeC - Nellis loam, 8 to 15 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-02_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Carpinus caroliniana*	20	Yes	FAC
2. *Quercus rubra*	10	Yes	FACU
3. *Prunus serotina*	5	No	FACU
4.			
5.			
6.			
7.			
	35	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus americana*	10	Yes	FACU
2. *Carpinus caroliniana*	5	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Fraxinus americana*	5	Yes	FACU
2. *Urtica dioica*	5	Yes	FAC
3. *Impatiens capensis*	5	Yes	FACW
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	15	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	5	Yes	FAC
2.			
3.			
4.			
	5	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	5	(A)
Total Number of Dominant Species Across All Strata:	8	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	62.5	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	5	x 2 =	10
FAC species	35	x 3 =	105
FACU species	30	x 4 =	120
UPL species	0	x 5 =	0
Column Totals	70	(A)	235 (B)
Prevalence Index = B/A =	3.4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-KCF-02_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 5/3	100					Silty Clay Loam	
10 - 20	10YR 6/3	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-17
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-03_PEM-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flood Plain **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR R **Lat:** 42.88903911 **Long:** -74.49672275 **Datum:** WGS84
Soil Map Unit Name: LaC- Lansing silt loam, 8 to 15 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-03

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	4	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-03_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	15	Yes	FACU
2. *Rosa multiflora*	10	Yes	FACU
3. *Rhamnus cathartica*	5	No	FAC
4.			
5.			
6.			
7.			
	30	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Euthamia graminifolia*	20	Yes	FAC
2. *Onoclea sensibilis*	10	Yes	FACW
3. *Impatiens capensis*	10	Yes	FACW
4. *Urtica dioica*	10	Yes	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	50	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	66.7	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	20	x 2 =	40
FAC species	35	x 3 =	105
FACU species	25	x 4 =	100
UPL species	0	x 5 =	0
Column Totals	80	(A)	245 (B)
Prevalence Index = B/A =	3.1		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-KCF-03_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 4/1	97	10YR 5/6	3	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery **Sampling Date:** 2021-Aug-17
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-03_UPL-1
Investigator(s): Kevin Ferguson , Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 15 to 20
Subregion (LRR or MLRA): LRR R **Lat:** 42.88902829 **Long:** -74.49681216 **Datum:** WGS84
Soil Map Unit Name: LaC - Lansing silt loam, 8 to 15 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-03_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus americana*	25	Yes	FACU
2. *Malus sp.*	10	Yes	NI
3. *Rhus glabra*	5	No	UPL
4.			
5.			
6.			
7.			
	40	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rhamnus cathartica*	25	Yes	FAC
2. *Ulmus rubra*	10	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	35	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Rhamnus cathartica*	5	Yes	FAC
2. *Euthamia graminifolia*	5	Yes	FAC
3. *Parthenocissus quinquefolia*	5	Yes	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	15	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	7	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	57.1	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	45	x 3 =	135
FACU species	30	x 4 =	120
UPL species	5	x 5 =	25
Column Totals	80	(A)	280 (B)
Prevalence Index = B/A =	3.5		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-KCF-03_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 5/3	100					Silt Loam	
12 - 20	10YR 4/2	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: New Bremen Solar **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-18
Applicant/Owner: AES **State:** NY **Sampling Point:** W-KCF-04_PEM-1
Investigator(s): Kevin Ferguson , Ben Corrigan **Section, Township, Range:** N/A
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 5 to 10
Subregion (LRR or MLRA): **Lat:** 42.8913621465 **Long:** -74.495408563 **Datum:** WGS84
Soil Map Unit Name: **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-04

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	8	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-04_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	80	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	80	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	80	x 2 =	160
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	80	(A)	160 (B)
Prevalence Index = B/A =	2		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-KCF-04_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 4/2	98	10YR 5/6	2	C	M	Silt Loam	
8 - 20	10YR 5/1	90	7.5R 4/8	10	C	M	Sandy Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-18
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-04_UPL-1
Investigator(s): Kevin Ferguson, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 10 to 20
Subregion (LRR or MLRA): LRR L **Lat:** 42.8912766 **Long:** -74.4951495 **Datum:** WGS84
Soil Map Unit Name: Rock Outcrop-Farmington association, RlF-very steep **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-04_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer rubrum*	20	Yes	FAC
2. *Quercus alba*	15	Yes	FACU
3. *Fagus grandifolia*	10	Yes	FACU
4. *Betula alleghaniensis*	5	No	FAC
5.			
6.			
7.			
	50	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Acer saccharum*	10	Yes	FACU
2. *Hamamelis virginiana*	5	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Fraxinus americana*	10	Yes	FACU
2. *Rubus idaeus*	5	Yes	FACU
3. *Urtica dioica*	5	Yes	FAC
4. *Poaceae*	5	Yes	NI
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	25	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 2 (A)

Total Number of Dominant Species Across All Strata: 9 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 22.2 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	30	x 3 =	90
FACU species	55	x 4 =	220
UPL species	0	x 5 =	0
Column Totals	85	(A)	310 (B)

Prevalence Index = B/A = 3.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-04_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 2	10YR 3/3	100					Loam	
2 - 14	10YR 6/3	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-18
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-05_PEM-1
Investigator(s): Kevin Ferguson, Abi Light **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8857064 **Long:** -74.4972165 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD-15-25% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-05

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-05_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus pennsylvanica*	10	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	80	Yes	FACW
2. *Euthamia graminifolia*	10	No	FAC
3. *Urtica dioica*	5	No	FAC
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	95	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	90	x 2 =	180
FAC species	15	x 3 =	45
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	105	(A)	225 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-KCF-05_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 5/1	98	10YR 5/8	2			Gravelly Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-18
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-05_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 10 to 20
Subregion (LRR or MLRA): LRR L **Lat:** 42.8855894 **Long:** -74.4973109 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD-8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-05_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Ostrya virginiana*	15	Yes	FACU
2. *Acer saccharum*	5	Yes	FACU
3. *Carya glabra*	5	Yes	FACU
4.			
5.			
6.			
7.			
	25	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carya glabra*	15	Yes	FACU
2. *Rubus idaeus*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	25	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Euthamia graminifolia*	40	Yes	FAC
2. *Fraxinus americana*	10	No	FACU
3. *Rosa multiflora*	5	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	55	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 6 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 16.7 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	40	x 3 =	120
FACU species	65	x 4 =	260
UPL species	0	x 5 =	0
Column Totals	105	(A)	380 (B)

Prevalence Index = B/A = 3.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-05_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 5/3	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-06_PEM-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8874439421 **Long:** -74.5011883043 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD-8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-06

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-06_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus pennsylvanica*	5	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	5	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rosa multiflora*	5	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	5	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	70	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	66.7	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	75	x 2 =	150
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	0	x 5 =	0
Column Totals	80	(A)	170 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-06_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10B 4/1	100					Silty Clay Loam	
6 - 20	10B 6/1	90	10R 3/6	10	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-06_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Foot slope **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8874219 **Long:** -74.5008569 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-06_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer rubrum*	40	Yes	FAC
2. *Ostrya virginiana*	5	No	FACU
3. *Tsuga canadensis*	5	No	FACU
4.			
5.			
6.			
7.			
	50	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fagus grandifolia*	50	Yes	FACU
2. *Hamamelis virginiana*	5	No	FACU
3.			
4.			
5.			
6.			
7.			
	55	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Rosa multiflora*	5	Yes	FACU
2. *Fraxinus americana*	5	Yes	FACU
3. *Urtica dioica*	5	Yes	FAC
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	15	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	40	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	45	x 3 =	135
FACU species	75	x 4 =	300
UPL species	0	x 5 =	0
Column Totals	120	(A)	435 (B)

Prevalence Index = B/A = 3.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-06_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 4/3	100					Silty Clay Loam	
6 - 20	10YR 5/3	100					Gravelly Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West