WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-07_PEM-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.885999 **Long:** -74.498344 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD-15-25% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-07

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	4

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-07_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phragmites australis*	100	Yes	FACW
2. *Impatiens capensis*	10	No	FACW
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	110	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	110	x 2 =	220
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	110	(A)	220 (B)
Prevalence Index = B/A =	2		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-KCF-07_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 4/2	100					Silty Clay Loam	
8 - 20	10B 4/1	90	10YR 5/6	10	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-07_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8859098 **Long:** -74.4984308 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaD, 15-25% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-07_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Rhus aromatica*	15	Yes	UPL
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rubus idaeus*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	90	Yes	FACU
2. *Parthenocissus quinquefolia*	10	No	FACU
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis aestivalis*	15	Yes	FACU
2. *Parthenocissus quinquefolia*	10	Yes	FACU
3.			
4.			
	25	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	140	x 4 =	560
UPL species	15	x 5 =	75
Column Totals	155	(A)	635 (B)
Prevalence Index = B/A =	4.1		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-07_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 4/3	100					Silty Clay Loam	
8 - 20	10YR 5/4	100					Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-08_PSS-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8848124855 **Long:** -74.4994768035 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC - 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-08

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-08_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera hirsuta*	20	Yes	FAC
2. *Rhamnus cathartica*	10	Yes	FAC
3. *Nyssa sylvatica*	10	Yes	FAC
4.			
5.			
6.			
7.			
	40	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	30	Yes	FACW
2. *Typha latifolia*	5	No	OBL
3. *Impatiens capensis*	5	No	FACW
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	40	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	35	x 2 =	70
FAC species	40	x 3 =	120
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	80	(A)	195 (B)

Prevalence Index = B/A = 2.4

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-08_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 16	10B 5/1	95	7.5R 5/6	5	C	M	Sandy Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Photo of Sample Plot North

Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-19
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-08_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Low Hill **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.884654 **Long:** -74.499594 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-08_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Pinus strobus*	60	Yes	FACU
2. *Fraxinus americana*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	80	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus americana*	15	Yes	FACU
2. *Rosa multiflora*	10	Yes	FACU
3. *Lonicera morrowii*	10	Yes	FACU
4.			
5.			
6.			
7.			
	35	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Fraxinus americana*	15	Yes	FACU
2. *Rubus idaeus*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	25	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 1 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 12.5 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	15	x 3 =	45
FACU species	140	x 4 =	560
UPL species	0	x 5 =	0
Column Totals	155	(A)	605 (B)

Prevalence Index = B/A = 3.9

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-08_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 4/3	65	7.5R 5/6	5	C	M	Silty Clay	
12 - 20	10YR 5/2	95	7.5R 5/6	5	C	M	Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Photo of Sample Plot North

Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-09_PSS-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8869086318 **Long:** -74.4963910897 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-09

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓_ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-09_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus pennsylvanica*	10	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rhamnus cathartica*	40	Yes	FAC
2. *Fraxinus pennsylvanica*	10	No	FACW
3. *Rosa multiflora*	10	No	FACU
4.			
5.			
6.			
7.			
	60	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	60	Yes	FACW
2. *Urtica dioica*	10	No	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Parthenocissus quinquefolia*	5	Yes	FACU
2. *Vitis riparia*	5	Yes	FAC
3.			
4.			
	10	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	80	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	80	x 2 =	160
FAC species	55	x 3 =	165
FACU species	15	x 4 =	60
UPL species	0	x 5 =	0
Column Totals	150	(A)	385 (B)

Prevalence Index = B/A = 2.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-09_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10B 4/1	95	7.5R 5/6	5	C	M	Silty Clay Loam	
10 - 20	10B 5/1	90	7.5R 5/6	10	C	M	Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-09_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.886962 **Long:** -74.496339 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-09_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Rhus aromatica*	30	Yes	UPL
2. *Acer negundo*	10	Yes	FAC
3. *Prunus serotina*	5	No	FACU
4.			
5.			
6.			
7.			
	45	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	15	Yes	FACU
2. *Acer negundo*	5	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	20	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	40	Yes	FACU
2. *Impatiens capensis*	25	Yes	FACW
3. *Rubus idaeus*	10	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	75	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Vitis riparia*	15	Yes	FAC
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	7	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	57.1	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	25	x 2 =	50
FAC species	30	x 3 =	90
FACU species	70	x 4 =	280
UPL species	30	x 5 =	150
Column Totals	155	(A)	570 (B)
Prevalence Index = B/A =	3.7		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-KCF-09_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 5/3	100					Silty Clay	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-10_PEM-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Swale **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.888564 **Long:** -74.498433 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-10

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
___ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-10_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phragmites australis*	100	Yes	FACW
2. *Symplocarpus foetidus*	5	No	OBL
3. *Rubus idaeus*	5	No	FACU
4. *Impatiens capensis*	5	No	FACW
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	115	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	105	x 2 =	210
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	0	x 5 =	0
Column Totals	115	(A)	235 (B)
Prevalence Index = B/A =	2		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-KCF-10_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10B 5/1	90	7.5R 5/6	10	C	M	Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met. Refusal due to coarse fragments.

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-10_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8885323 **Long:** -74.4986099 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ____	Depth (inches):	
Water Table Present?	Yes ____ No ____	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ____	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-10_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	60	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	60	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	10	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	20	Yes	FACU
2. *Parthenocissus quinquefolia*	20	Yes	FACU
3. *Urtica dioica*	10	No	FAC
4. *Rubus idaeus*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	60	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1. *Parthenocissus quinquefolia*	15	Yes	FACU
2.			
3.			
4.			
	15	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	135	x 4 =	540
UPL species	0	x 5 =	0
Column Totals	145	(A)	570 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-10_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 5/3	100					Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-11_PEM-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8890773235 **Long:** -74.5004537144 **Datum:** WGS84
Soil Map Unit Name: Rock outcrop-Farmington association, RLF, very steep **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-11

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
___ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
_✓ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	1
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-11_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Hamamelis virginiana*	10	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	30	Yes	FACW
2. *Urtica dioica*	10	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	40	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	66.7	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	30	x 2 =	60
FAC species	10	x 3 =	30
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	50	(A)	130 (B)
Prevalence Index = B/A =	2.6		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-KCF-11_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 14	10B 5/1	85	7.5R 5/6	15	C	M	Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-11_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.889216 **Long:** -74.500167 **Datum:** WGS84
Soil Map Unit Name: Rock outcrop-Farmington association, RLF, very steep **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-11_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fagus grandifolia*	30	Yes	FACU
2. *Acer saccharum*	20	Yes	FACU
3. *Tsuga canadensis*	20	Yes	FACU
4.			
5.			
6.			
7.			
	70	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fagus grandifolia*	20	Yes	FACU
2. *Acer saccharum*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	30	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1. *Parthenocissus quinquefolia*	40	Yes	FACU
2. *Athyrium angustum*	15	Yes	FAC
3. *Urtica dioica*	10	No	FAC
4. *Impatiens capensis*	5	No	FACW
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	7	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	14.3	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	5	x 2 =	10
FAC species	25	x 3 =	75
FACU species	140	x 4 =	560
UPL species	0	x 5 =	0
Column Totals	170	(A)	645 (B)
Prevalence Index = B/A =	3.8		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-11_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/3	100					Silty Clay Loam	
-								
-								
-								
-								
-								
-								
-								
-								
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met. Refusal due to coarse fragments.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-KCF-12_PEM-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 2 to 5
Subregion (LRR or MLRA): LRR L **Lat:** 42.8879645421 **Long:** -74.4984039199 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-KCF-12

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
_✓_ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	6

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met. A positive indication of wetland hydrology was observed (primary and secondary indicators were present).

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-12_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	40	Yes	FACW
2. *Typha latifolia*	20	Yes	OBL
3. *Phalaris arundinacea*	5	No	FACW
4. *Solidago canadensis*	5	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	20	x 1 =	20
FACW species	45	x 2 =	90
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	0	x 5 =	0
Column Totals	70	(A)	130 (B)
Prevalence Index = B/A =	1.9		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC). A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00). A positive indication of hydrophytic vegetation was observed (Rapid Test for Hydrophytic Vegetation).

SOIL

Sampling Point: W-KCF-12_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 4/2	100	10YR 4/1				Silty Clay	
8 - 16	10B 4/1	90	10YR 5/6	10	C	M	Silty Clay	
16 - 20	10B 5/1	85	10YR 5/8	15	C	M	Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed. The criterion for hydric soil is met.

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-20
Applicant/Owner: SunEast **State:** New York **Sampling Point:** W-KCF-12_UPL-1
Investigator(s): Kevin Ferguson, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8880001 **Long:** -74.4986368 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, LaC, 8-15% slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met. No positive indication of wetland hydrology was observed.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-KCF-12_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	70	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	70	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus americana*	10	Yes	FACU
2. *Carpinus caroliniana*	10	Yes	FAC
3. *Rosa multiflora*	5	Yes	FACU
4.			
5.			
6.			
7.			
	25	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	15	Yes	FACU
2. *Ageratina altissima*	15	Yes	FACU
3. *Fraxinus americana*	5	No	FACU
4. *Phytolacca americana*	5	No	FACU
5. *Parthenocissus quinquefolia*	5	No	FACU
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	45	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	16.7	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	130	x 4 =	520
UPL species	0	x 5 =	0
Column Totals	140	(A)	550 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-KCF-12_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 5/3	100					Silty Clay Loam	
12 - 20	10YR 5/4	100					Silty Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed. The criterion for hydric soil is not met.

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Canajoharie, Montgomery County **Sampling Date:** 2022-July-06
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-01_PEM-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8874565 **Long:** -74.5495908333 **Datum:** WGS84
Soil Map Unit Name: Ma - Madalin silty clay loam **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-01

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓_ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-01_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lythrum salicaria*	50	Yes	OBL
2. *Carex vulpinoidea*	20	Yes	OBL
3. *Scirpus atrovirens*	10	No	OBL
4. *Onoclea sensibilis*	10	No	FACW
5. *Typha latifolia*	10	No	OBL
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	90	x 1 =	90
FACW species	10	x 2 =	20
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	100	(A)	110 (B)
Prevalence Index = B/A =	1.1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-01_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 7	10YR 3/1	100					Clay Loam	
7 - 14	10YR 3/1	98	2.5YR 6/4	2	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Soil Photos



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Canajoharie, Montgomery County **Sampling Date:** 2022-July-06
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-01_PSS-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8874141667 **Long:** -74.549705 **Datum:** WGS84
Soil Map Unit Name: Ma - Madalin silty clay loam **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-01

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓_ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-01_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus racemosa*	20	Yes	FAC
2. *Viburnum lentago*	20	Yes	FAC
3. *Salix eriocephala*	20	Yes	FACW
4.			
5.			
6.			
7.			
	60	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	10	Yes	FACW
2. *Eutrochium purpureum*	10	Yes	FAC
3. *Equisetum fluviatile*	10	Yes	OBL
4. *Typha latifolia*	10	Yes	OBL
5. *Impatiens capensis*	10	Yes	FACW
6. *Symphyotrichum lanceolatum*	10	Yes	FACW
7.			
8.			
9.			
10.			
11.			
12.			
	60	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	9	(A)
Total Number of Dominant Species Across All Strata:	9	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	20	x 1 =	20
FACW species	50	x 2 =	100
FAC species	50	x 3 =	150
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	120	(A)	270 (B)

Prevalence Index = B/A = 2.3

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-01_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/1	100					Clay Loam	
6 - 18	10YR 3/1	98	2.5YR 6/4	2	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Canajoharie, Montgomery County **Sampling Date:** 2022-July-06
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-01_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8874393333 **Long:** -74.549522 **Datum:** WGS84
Soil Map Unit Name: Ma - Madalin silty clay loam **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to mowing of vegetation.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	13

Wetland Hydrology Present? Yes ____ No _✓_

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-01_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Poa pratensis*	40	Yes	FACU
2. *Trifolium pratense*	5	No	FACU
3. *Trifolium repens*	5	No	FACU
4. *Plantago major*	5	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	55	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	55	x 4 =	220
UPL species	0	x 5 =	0
Column Totals	55	(A)	220 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Pasture.

SOIL

Sampling Point: W-MLM-01_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 7	10YR 3/1	100					Loam	
7 - 14	10YR 3/1	98	2.5YR 6/4	2	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos



Vegetation Photos



Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Canajoharie, Montgomery County **Sampling Date:** 2022-July-06
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-02_PEM-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8887223333 **Long:** -74.551656 **Datum:** WGS84
Soil Map Unit Name: ChB - Churchville silty clay loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-02

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓_ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
_✓_ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-02_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	45	Yes	FACW
2. *Lythrum salicaria*	20	Yes	OBL
3. *Onoclea sensibilis*	20	Yes	FACW
4. *Impatiens capensis*	10	No	FACW
5. *Persicaria sagittata*	5	No	OBL
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	25	x 1 =	25
FACW species	75	x 2 =	150
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	100	(A)	175 (B)
Prevalence Index = B/A =	1.8		

Hydrophytic Vegetation Indicators:

- ✓ 1- Rapid Test for Hydrophytic Vegetation
- ✓ 2 - Dominance Test is >50%
- ✓ 3 - Prevalence Index is ≤ 3.0[1]
- ____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
- ____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-02_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/1	96	10YR 5/6	4	C	M/PL	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



Soil Photos

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Canajoharie, Montgomery County **Sampling Date:** 2022-July-06
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-02_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8886635288 **Long:** -74.5516007347 **Datum:** WGS84
Soil Map Unit Name: ChB - Churchville silty clay loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-02_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	90	Yes	UPL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	90	x 5 =	450
Column Totals	90	(A)	450 (B)
Prevalence Index = B/A =	5		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field.

SOIL

Sampling Point: W-MLM-02_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/2	100					Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-03_PEM-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.847982338 **Long:** -74.4601265633 **Datum:** WGS84
Soil Map Unit Name: IlA - Ilion silt loam, 0 to 3 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation _✓_, Soil ___, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No _✓_
Are Vegetation ___, Soil ___, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-03

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓_ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-03_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Salix cordata*	30	Yes	FAC
2.			
3.			
4.			
5.			
6.			
7.			
	30	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha latifolia*	30	Yes	OBL
2. *Onoclea sensibilis*	30	Yes	FACW
3. *Phalaris arundinacea*	30	Yes	FACW
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	30	x 1 =	30
FACW species	60	x 2 =	120
FAC species	30	x 3 =	90
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	120	(A)	240 (B)
Prevalence Index = B/A =	2		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field.

SOIL

Sampling Point: W-MLM-03_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 3/1	100					Loam	
4 - 18	10YR 2/1	85	10YR 3/6	10	C	M	Clay Loam	
4 - 18			N 2.5/					

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-03_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8480548555 **Long:** -74.4599484292 **Datum:** WGS84
Soil Map Unit Name: IlA - Ilion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-03_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	50	Yes	UPL
2. *Phalaris arundinacea*	35	Yes	FACW
3. *Fragaria virginiana*	10	No	FACU
4. *Lythrum salicaria*	5	No	OBL
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	35	x 2 =	70
FAC species	0	x 3 =	0
FACU species	10	x 4 =	40
UPL species	50	x 5 =	250
Column Totals	100	(A)	365 (B)
Prevalence Index = B/A =	3.7		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field.

SOIL

Sampling Point: W-MLM-03_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 14	10YR 3/2	100					Loam	
14 - 16	10YR 3/2	98	2.5YR 6/4	2	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-04_PEM-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Hillslope **Local relief (concave, convex, none):** Concave **Slope (%):** 1 to 3
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8445298566 **Long:** -74.4618717085 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-04

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓_ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-04_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha angustifolia*	25	Yes	OBL
2. *Phalaris arundinacea*	20	Yes	FACW
3. *Onoclea sensibilis*	15	Yes	FACW
4. *Carex vulpinoidea*	10	No	OBL
5. *Eutrochium purpureum*	10	No	FAC
6. *Melilotus officinalis*	10	No	FACU
7. *Equisetum arvense*	10	No	FAC
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	35	x 1 =	35
FACW species	35	x 2 =	70
FAC species	20	x 3 =	60
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	100	(A)	205 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

- ✓ 1- Rapid Test for Hydrophytic Vegetation
- ✓ 2 - Dominance Test is >50%
- ✓ 3 - Prevalence Index is ≤ 3.0[1]
- ____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
- ✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-04_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 14	10YR 3/1	98	2.5YR 6/4	2	C	M/PL	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-04_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8438253987 **Long:** -74.4617536035 **Datum:** WGS84
Soil Map Unit Name: Ma - Madalin silty clay loam **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-04

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
_✓_ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
_✓_ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-04_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus nigra*	40	Yes	FACW
2. *Carpinus caroliniana*	30	Yes	FAC
3. *Betula alleghaniensis*	30	Yes	FAC
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carpinus caroliniana*	20	Yes	FAC
2.			
3.			
4.			
5.			
6.			
7.			
	20	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Carex stricta*	50	Yes	OBL
2. *Laportea canadensis*	20	Yes	FACW
3. *Caltha palustris*	10	No	OBL
4. *Impatiens capensis*	5	No	FACW
5. *Onoclea sensibilis*	5	No	FACW
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	6	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	60	x 1 =	60
FACW species	70	x 2 =	140
FAC species	80	x 3 =	240
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	210	(A)	440 (B)
Prevalence Index = B/A =	2.1		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-04_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 5	10YR 2/1	98	2.5YR 6/4	2	C	PL	Silty Clay Loam	
5 - 14	10YR 8/4	98	2.5YR 6/4	2	C	M	Sandy Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-04_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 1 to 3
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.844773 **Long:** -74.4617515 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present. Circumstances are not normal due to agricultural activities.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-04_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	90	Yes	UPL
2. *Phalaris arundinacea*	10	No	FACW
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	10	x 2 =	20
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	90	x 5 =	450
Column Totals	100	(A)	470 (B)
Prevalence Index = B/A =	4.7		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

Active agricultural field.

SOIL

Sampling Point: W-MLM-04_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 5	10YR 3/4	100					Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: Rock
Depth (inches): 5

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Vegetation Photos



Soil Photos

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-04_UPL-2
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 1 to 3
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8435269697 **Long:** -74.4615648696 **Datum:** WGS84
Soil Map Unit Name: Ma - Madalin silty clay loam **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-04_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Pinus strobus*	80	Yes	FACU
2. *Tsuga canadensis*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Aralia nudicaulis*	30	Yes	FACU
2. *Dryopteris intermedia*	20	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	50	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	25	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	20	x 3 =	60
FACU species	130	x 4 =	520
UPL species	0	x 5 =	0
Column Totals	150	(A)	580 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ _____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-04_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 7	10YR 3/3	100					Fibric Peat	
7 - 12	2.5Y 7/2	100					Loamy Sand	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North

Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-08
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-05_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.841317 **Long:** -74.4600936667 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-05

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
_✓_ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	1	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-05_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Betula alleghaniensis*	60	Yes	FAC
2. *Acer rubrum*	20	Yes	FAC
3. *Fraxinus pennsylvanica*	10	No	FACW
4. *Tsuga canadensis*	10	No	FACU
5.			
6.			
7.			
	100	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Fraxinus pennsylvanica*	10	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	3	No	FACW
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	3	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	23	x 2 =	46
FAC species	80	x 3 =	240
FACU species	10	x 4 =	40
UPL species	0	x 5 =	0
Column Totals	113	(A)	326 (B)
Prevalence Index = B/A =	2.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-05_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/1	100					Mucky Peat	
6 - 18	10YR 2/1	97	10YR 5/6	2	C	M	Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-08
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-05_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8412708333 **Long:** -74.4601488333 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-05_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer rubrum*	60	Yes	FAC
2. *Tsuga canadensis*	40	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Toxicodendron radicans*	20	Yes	FAC
2. *Adiantum pedatum*	20	Yes	FACU
3. *Polystichum acrostichoides*	20	Yes	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	60	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	40	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	80	x 3 =	240
FACU species	80	x 4 =	320
UPL species	0	x 5 =	0
Column Totals	160	(A)	560 (B)
Prevalence Index = B/A =	3.5		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-05_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 2/1	98	10YR 5/6	2	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: Rock
Depth (inches): 6

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-06_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8401015 **Long:** -74.4601005 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-06

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
_✓_ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-06_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	40	Yes	FACU
2. *Betula alleghaniensis*	40	Yes	FAC
3. *Acer saccharum*	10	No	FACU
4. *Carya ovata*	10	No	FACU
5.			
6.			
7.			
	100	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	0	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	40	x 3 =	120
FACU species	60	x 4 =	240
UPL species	0	x 5 =	0
Column Totals	100	(A)	360 (B)
Prevalence Index = B/A =	3.6		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-06_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 2/1	100					Clay Loam	
4 - 16	N 6/	60	10YR 7/6	40			Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
_✓_ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
_✓_ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-06_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.840133 **Long:** -74.4601508333 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-06_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	60	Yes	FACU
2. *Acer saccharum*	40	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	0	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	100	x 4 =	400
UPL species	0	x 5 =	0
Column Totals	100	(A)	400 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-06_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 3	10YR 6/2	100					Fibric Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: Root
Depth (inches): 3

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Soil Photos

Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-07_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8395899037 **Long:** -74.4626162326 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-07

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-07_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	20	Yes	FACU
2. *Acer rubrum*	20	Yes	FAC
3. *Betula alleghaniensis*	20	Yes	FAC
4.			
5.			
6.			
7.			
	60	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lindera benzoin*	10	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	20	Yes	FACW
2. *Toxicodendron radicans*	10	Yes	FAC
3. *Parthenocissus quinquefolia*	5	No	FACU
4. *Acer rubrum*	5	No	FAC
5. *Betula alleghaniensis*	5	No	FAC
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	45	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	5	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	83.3	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	30	x 2 =	60
FAC species	60	x 3 =	180
FACU species	25	x 4 =	100
UPL species	0	x 5 =	0
Column Totals	115	(A)	340 (B)
Prevalence Index = B/A =	3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-07_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 10	10YR 2/1	90	10YR 6/6	10	C	M	Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



Soil Photos



Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-07_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8397333333 **Long:** -74.4627273333 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-07_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	60	Yes	FACU
2. *Pinus strobus*	30	Yes	FACU
3. *Fagus grandifolia*	10	No	FACU
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Acer pensylvanicum*	10	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Dryopteris intermedia*	10	Yes	FAC
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	10	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	25	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	110	x 4 =	440
UPL species	0	x 5 =	0
Column Totals	120	(A)	470 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ _____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-07_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/3						Fibric Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: Root
Depth (inches): 6

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot
West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-08_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8399738333 **Long:** -74.463269 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:** None
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-08

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-08_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus pennsylvanica*	40	Yes	FACW
2. *Tsuga canadensis*	40	Yes	FACU
3. *Acer saccharum*	10	No	FACU
4.			
5.			
6.			
7.			
	90	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Carpinus caroliniana*	20	Yes	FAC
2.			
3.			
4.			
5.			
6.			
7.			
	20	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	5	Yes	FACW
2. *Toxicodendron radicans*	5	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	10	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	80	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	45	x 2 =	90
FAC species	25	x 3 =	75
FACU species	50	x 4 =	200
UPL species	0	x 5 =	0
Column Totals	120	(A)	365 (B)
Prevalence Index = B/A =	3		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (>50% of dominant species indexed as OBL, FACW, or FAC).

SOIL

Sampling Point: W-MLM-08_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 5	10YR 2/1	100					Fibric Mucky Peat	
5 - 12	10YR 2/1	98	10YR 6/6	2	C	M	Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos



Vegetation Photos



Soil Photos

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-11
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-08_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.840044 **Long:** -74.4632425 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-08_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	80	Yes	FACU
2. *Acer rubrum*	10	No	FAC
3.			
4.			
5.			
6.			
7.			
	90	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	0	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	80	x 4 =	320
UPL species	0	x 5 =	0
Column Totals	90	(A)	350 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-08_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 2/1						Clay Loam	
6 - 12	10YR 2/1	98	10YR 6/6	2	C	M	Clay	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos

Soil Photos

Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-09_PFO-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8404214098 **Long:** -74.4634750782 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-MLM-09

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO. Area is wetland, all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
_✓_ Sparsely Vegetated Concave Surface (B8)
_✓_ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
_✓_ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
_✓_ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-09_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus pennsylvanica*	40	Yes	FACW
2. *Fagus grandifolia*	15	Yes	FACU
3. *Tsuga canadensis*	15	Yes	FACU
4. *Acer saccharum*	10	No	FACU
5.			
6.			
7.			
	80	= Total Cover	

Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	

Herb Stratum (Plot size: 5 ft)			
1. *Onoclea sensibilis*	5	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	5	= Total Cover	

Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	45	x 2 =	90
FAC species	0	x 3 =	0
FACU species	40	x 4 =	160
UPL species	0	x 5 =	0
Column Totals	85	(A)	250 (B)

Prevalence Index = B/A = 2.9

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

A positive indication of hydrophytic vegetation was observed (Prevalence Index is ≤ 3.00).

SOIL

Sampling Point: W-MLM-09_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 2/1	97	10YR 6/6	3	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

A positive indication of hydric soil was observed.

Hydrology Photos

Vegetation Photos



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2022-July-19
Applicant/Owner: Suneast **State:** NY **Sampling Point:** W-MLM-09_UPL-1
Investigator(s): Melanie Musarra **Section, Township, Range:**
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): MLRA 144A of LRR R **Lat:** 42.8402603094 **Long:** -74.4634617905 **Datum:** WGS84
Soil Map Unit Name: ApB - Appleton silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL. Area is upland, not all three wetland parameters are present.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:
The criterion for wetland hydrology is not met.

VEGETATION -- Use scientific names of plants.

Sampling Point: W-MLM-09_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	90	Yes	FACU
2. *Fagus grandifolia*	10	No	FACU
3.			
4.			
5.			
6.			
7.			
	100	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Tsuga canadensis*	10	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	0	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	110	x 4 =	440
UPL species	0	x 5 =	0
Column Totals	110	(A)	440 (B)
Prevalence Index = B/A =	4		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

✓ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

No positive indication of hydrophytic vegetation was observed (≥50% of dominant species indexed as FAC− or drier).

SOIL

Sampling Point: W-MLM-09_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 3	10YR 2/2	100					Peat	
3 - 7	2.5Y 7/1	100					Silt	
7 - 12	2.5Y 6/4	100					Silt	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

No positive indication of hydric soils was observed.

Hydrology Photos

Vegetation Photos

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East

Photo of Sample Plot South

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-01_PEM-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8676056117 **Long:** -74.4788922743 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-01

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes _✓_ No ____	Depth (inches):	10	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	6	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-01_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha angustifolia*	40	Yes	OBL
2. *Lythrum salicaria*	25	Yes	OBL
3. *Dipsacus laciniatus*	20	No	FACU
4. *Phalaris arundinacea*	10	No	FACW
5. *Euthamia graminifolia*	10	No	FAC
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	105	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	65	x 1 =	65
FACW species	10	x 2 =	20
FAC species	10	x 3 =	30
FACU species	20	x 4 =	80
UPL species	0	x 5 =	0
Column Totals	105	(A)	195 (B)
Prevalence Index = B/A =	1.9		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-01_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 18	10YR 4/2	95	10YR 5/8	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
_✓_ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-01_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Low Hill **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8672265402 **Long:** -74.4787786995 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):	
Water Table Present?	Yes ____ No ✓	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-01_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Medicago sativa*	60	Yes	UPL
2. *Phleum pratense*	25	Yes	FACU
3. *Poa pratensis*	10	No	FACU
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	95	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	35	x 4 =	140
UPL species	60	x 5 =	300
Column Totals	95	(A)	440 (B)

Prevalence Index = B/A = 4.6

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-01_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 6	10YR 3/3	100					Silt Loam	
6 - 18	10YR 3/4	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot South



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-02_PEM-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8701628885 **Long:** -74.4781095722 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-02

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	2
Water Table Present?	Yes _✓_ No ____	Depth (inches):	6
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-02_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Glyceria striata*	60	Yes	OBL
2. *Typha angustifolia*	20	Yes	OBL
3. *Lythrum salicaria*	10	No	OBL
4. *Lysimachia nummularia*	10	No	FACW
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	100	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	90	x 1 =	90
FACW species	10	x 2 =	20
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	100	(A)	110 (B)
Prevalence Index = B/A =	1.1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-02_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 4	10YR 3/2	100					Clay Loam	
4 - 20	10YR 3/2	95	2.5YR 4/6	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Hydrology Photos



Soil Photos



Photo of Sample Plot East



Photo of Sample Plot South



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-02_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8701600386 **Long:** -74.4780579396 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-02_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Medicago sativa*	75	Yes	UPL
2. *Phleum pratense*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	95	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	20	x 4 =	80
UPL species	75	x 5 =	375
Column Totals	95	(A)	455 (B)
Prevalence Index = B/A =	4.8		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-02_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 3/2	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-03_PEM-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8719755588 **Long:** -74.4776104298 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, 15 to 25 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-03

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
_✓_ High Water Table (A2)
_✓_ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes _✓_ No ____	Depth (inches):	5
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-03_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	35	Yes	FACW
2. *Epilobium palustre*	25	Yes	OBL
3. *Typha angustifolia*	15	No	OBL
4. *Eupatorium perfoliatum*	5	No	FACW
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	80	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	40	x 1 =	40
FACW species	40	x 2 =	80
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	80	(A)	120 (B)
Prevalence Index = B/A =	1.5		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-03_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 3/2	90	7.5YR 4/6	10	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Hydrology Photos



Soil Photos



Photo of Sample Plot North

Photo of Sample Plot West

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-03_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Toe **Local relief (concave, convex, none):** Convex **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8716629558 **Long:** -74.4777053968 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, 15 to 25 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes ✓ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ✓ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No ✓		
Hydric Soil Present?	Yes ____ No ✓	**Is the Sampled Area within a Wetland?**	**Yes ____ No ✓**
Wetland Hydrology Present?	Yes ____ No ✓	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No ✓	Depth (inches):		
Water Table Present?	Yes ____ No ✓	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No ✓
Saturation Present? (includes capillary fringe)	Yes ____ No ✓	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-03_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Tsuga canadensis*	30	Yes	FACU
2. *Acer saccharum*	15	Yes	FACU
3. *Ostrya virginiana*	10	No	FACU
4.			
5.			
6.			
7.			
	55	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Hamamelis virginiana*	5	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	5	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Parthenocissus quinquefolia*	50	Yes	FACU
2. *Amphicarpaea bracteata*	10	No	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	60	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: **0** (A)

Total Number of Dominant Species Across All Strata: **4** (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: **0** (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	10	x 3 =	30
FACU species	110	x 4 =	440
UPL species	0	x 5 =	0
Column Totals	120	(A)	470 (B)

Prevalence Index = B/A = 3.9

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-03_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 14	10YR 3/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Digging restriction due to roots.

Soil Photos



Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-04_PEM-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8705936345 **Long:** -74.4750333299 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, 15 to 25 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-04

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	2
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-04_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Leersia oryzoides*	40	Yes	OBL
2. *Impatiens capensis*	20	Yes	FACW
3. *Juncus effusus*	12	No	OBL
4. *Euthamia graminifolia*	7	No	FAC
5. *Typha angustifolia*	5	No	OBL
6. *Mentha arvensis*	5	No	FACW
7.			
8.			
9.			
10.			
11.			
12.			
	89	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	57	x 1 =	57
FACW species	25	x 2 =	50
FAC species	7	x 3 =	21
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	89	(A)	128 (B)
Prevalence Index = B/A =	1.4		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-04_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 18	10YR 3/2	90	5YR 4/6	10	C	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Hydrology Photos

Soil Photos



Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-04_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Toe **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8708273219 **Long:** -74.4759460353 **Datum:** WGS84
Soil Map Unit Name: Lansing silt loam, 15 to 25 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-04_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Acer saccharum*	25	Yes	FACU
2. *Tsuga canadensis*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	45	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Hamamelis virginiana*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Amphicarpaea bracteata*	20	Yes	FAC
2. *Impatiens capensis*	10	Yes	FACW
3. *Polystichum acrostichoides*	5	No	FACU
4. *Parathelypteris noveboracensis*	5	No	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	40	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	40	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	10	x 2 =	20
FAC species	25	x 3 =	75
FACU species	65	x 4 =	260
UPL species	0	x 5 =	0
Column Totals	100	(A)	355 (B)
Prevalence Index = B/A =	3.6		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-04_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/2	100					Silt Loam	
8 - 20	10YR 3/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil Photos

Photo of Sample Plot North

Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_PEM-2
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8653264046 **Long:** -74.4772630838 **Datum:** WGS84
Soil Map Unit Name: Water **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-05

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	6
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_PEM-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Leersia oryzoides*	35	Yes	OBL
2. *Bidens frondosa*	30	Yes	FACW
3. *Typha angustifolia*	20	Yes	OBL
4. *Impatiens capensis*	10	No	FACW
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	95	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	3	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	55	x 1 =	55
FACW species	40	x 2 =	80
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	95	(A)	135 (B)

Prevalence Index = B/A = 1.4

Hydrophytic Vegetation Indicators:

- ✓ 1- Rapid Test for Hydrophytic Vegetation
- ✓ 2 - Dominance Test is >50%
- ✓ 3 - Prevalence Index is ≤ 3.0[1]
- ____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
- ____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_PEM-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric.

Hydrology Photos



Photo of Sample Plot East



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_PSS-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8653100599 **Long:** -74.47651173 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-05

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PSS.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_PSS-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Salix alba*	40	Yes	FACW
2. *Cornus racemosa*	15	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	55	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	35	Yes	FACW
2. *Cornus racemosa*	15	Yes	FAC
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	50	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	75	x 2 =	150
FAC species	30	x 3 =	90
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	105	(A)	240 (B)

Prevalence Index = B/A = 2.3

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_PSS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 12	10YR 3/2	95	10YR 4/6	5	C	M	Silt Loam	
12 - 20	10YR 3/2	95	10YR 4/1	5	D	M	Silty Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Soil Photos



Photo of Sample Plot South



Photo of Sample Plot
West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-27
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_PUB-3
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8656477249 **Long:** -74.484609319 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-05

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	48
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_PUB-3

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha angustifolia*	5	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	5	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	5	(A)	5 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_PUB-3

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric.

Hydrology Photos



Photo of Sample Plot North



Photo of Sample Plot East



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Low Hill **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8655302944 **Long:** -74.476632597 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Lonicera morrowii*	30	Yes	FACU
2. *Cornus racemosa*	10	Yes	FAC
3.			
4.			
5.			
6.			
7.			
	40	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Cornus racemosa*	20	Yes	FAC
2. *Rhamnus cathartica*	10	Yes	FAC
3. *Fragaria vesca*	5	No	UPL
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	35	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	4	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	75	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	40	x 3 =	120
FACU species	30	x 4 =	120
UPL species	5	x 5 =	25
Column Totals	75	(A)	265 (B)
Prevalence Index = B/A =	3.5		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 11	10YR 3/2	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Digging restriction due to roots .

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-25
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_UPL-2
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8653915739 **Long:** -74.4772320707 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_UPL-2

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Medicago sativa*	30	Yes	UPL
2. *Solidago canadensis*	25	Yes	FACU
3. *Asclepias syriaca*	15	No	UPL
4. *Mentha arvensis*	10	No	FACW
5. *Daucus carota*	5	No	UPL
6. *Phalaris arundinacea*	5	No	FACW
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	15	x 2 =	30
FAC species	0	x 3 =	0
FACU species	25	x 4 =	100
UPL species	50	x 5 =	250
Column Totals	90	(A)	380 (B)
Prevalence Index = B/A =	4.2		

Hydrophytic Vegetation Indicators:

_____ 1- Rapid Test for Hydrophytic Vegetation

_____ 2 - Dominance Test is > 50%

_____ 3 - Prevalence Index is ≤ 3.0[1]

_____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

_____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_UPL-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 18	10YR 4/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil Photos



Photo of Sample Plot East



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-27
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-05_UPL-3
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** None **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.86506732 **Long:** -74.4848000911 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-05_UPL-3

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Solidago canadensis*	60	Yes	FACU
2. *Phalaris arundinacea*	15	No	FACW
3. *Asclepias syriaca*	10	No	UPL
4. *Lotus tenuis*	10	No	FACU
5. *Daucus carota*	5	No	UPL
6. *Lonicera morrowii*	5	No	FACU
7.			
8.			
9.			
10.			
11.			
12.			
	105	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	15	x 2 =	30
FAC species	0	x 3 =	0
FACU species	75	x 4 =	300
UPL species	15	x 5 =	75
Column Totals	105	(A)	405 (B)
Prevalence Index = B/A =	3.9		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-05_UPL-3

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 7	10YR 3/3	100					Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Digging restriction due to shallow gravel.

Soil Photos



Photo of Sample Plot South



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-26
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-06_PFO-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.862856132 **Long:** -74.4894221239 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-06

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PFO.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-06_PFO-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus nigra*	60	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	60	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Cornus racemosa*	15	Yes	FAC
2. *Lonicera morrowii*	10	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	25	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Impatiens capensis*	40	Yes	FACW
2. *Onoclea sensibilis*	25	Yes	FACW
3. *Leersia oryzoides*	15	No	OBL
4. *Rosa multiflora*	10	No	FACU
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	90	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	4	(A)
Total Number of Dominant Species Across All Strata:	5	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	80	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	15	x 1 =	15
FACW species	125	x 2 =	250
FAC species	15	x 3 =	45
FACU species	20	x 4 =	80
UPL species	0	x 5 =	0
Column Totals	175	(A)	390 (B)

Prevalence Index = B/A = 2.2

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

_✓_ 2 - Dominance Test is >50%

_✓_ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes _✓_ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-06_PFO-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 3/1	95	5YR 4/6	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot South

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-26
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-06_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8629413341 **Long:** -74.4889876899 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):		
Water Table Present?	Yes ____ No _✓_	Depth (inches):		**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):		

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-06_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus nigra*	40	Yes	FACW
2. *Prunus serotina*	20	Yes	FACU
3.			
4.			
5.			
6.			
7.			
	60	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Rhamnus cathartica*	15	Yes	FAC
2. *Fraxinus nigra*	5	Yes	FACW
3.			
4.			
5.			
6.			
7.			
	20	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Parthenocissus quinquefolia*	50	Yes	FACU
2. *Rubus allegheniensis*	20	Yes	FACU
3. *Impatiens capensis*	10	No	FACW
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	80	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	3	(A)
Total Number of Dominant Species Across All Strata:	6	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	50	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	55	x 2 =	110
FAC species	15	x 3 =	45
FACU species	90	x 4 =	360
UPL species	0	x 5 =	0
Column Totals	160	(A)	515 (B)

Prevalence Index = B/A = 3.2

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-06_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 8	10YR 3/2	100					Silt Loam	
8 - 20	10YR 4/2	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-26
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-07_PUB-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.863525888 **Long:** -74.4895901811 **Datum:** WGS84
Soil Map Unit Name: Water **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-07

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	48
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-07_PUB-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Typha angustifolia*	5	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	5	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	5	x 1 =	5
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	5	(A)	5 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-07_PUB-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric.

Hydrology Photos



Photo of Sample Plot East



Photo of Sample Plot South



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-26
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-07_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Flat **Local relief (concave, convex, none):** Undulating **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8634700645 **Long:** -74.4893521351 **Datum:** WGS84
Soil Map Unit Name: Water **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes ____ No _✓_**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-07_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1. *Fraxinus americana*	15	Yes	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	15	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Tilia americana*	3	No	FACU
2.			
3.			
4.			
5.			
6.			
7.			
	3	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Zea mays*	40	Yes	UPL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	40	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	18	x 4 =	72
UPL species	40	x 5 =	200
Column Totals	58	(A)	272 (B)
Prevalence Index = B/A =	4.7		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-07_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 9	7.5YR 3/2	100					Silty Clay Loam	
9 - 18	7.5YR 3/2	95	10YR 4/6	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Soil Photos



Photo of Sample Plot East



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-27
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-08_PUB-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8640522715 **Long:** -74.4817194064 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-08

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PUB.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

_✓ Surface Water (A1)
_✓ High Water Table (A2)
_✓ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
_✓ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes _✓_ No ____	Depth (inches):	60
Water Table Present?	Yes _✓_ No ____	Depth (inches):	0
Saturation Present? (includes capillary fringe)	Yes _✓_ No ____	Depth (inches):	0

Wetland Hydrology Present? Yes _✓_ No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-08_PUB-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lemna minor*	70	Yes	OBL
2.			
3.			
4.			
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	70	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	1	(A)
Total Number of Dominant Species Across All Strata:	1	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	70	x 1 =	70
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	70	(A)	70 (B)
Prevalence Index = B/A =	1		

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-08_PUB-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
-								

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
_✓_ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes _✓_ No ____

Remarks:

Due to inundation a clear soil profile was unobtainable. Soils are assumed to be hydric.

Hydrology Photos



Photo of Sample Plot North



Photo of Sample Plot West



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Aug-27
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-08_UPL-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Hilltop **Local relief (concave, convex, none):** Convex **Slope (%):** 1 to 3
Subregion (LRR or MLRA): LRR L **Lat:** 42.8649435612 **Long:** -74.4821268507 **Datum:** WGS84
Soil Map Unit Name: Illion silt loam, 0 to 3 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____ No _✓_		
Hydric Soil Present?	Yes ____ No _✓_	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes ____ No _✓_	**If yes, optional Wetland Site ID:**	W-NSD-08

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is UPL.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
___ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
___ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes ____ No _✓_
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-08_UPL-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Lotus tenuis*	60	Yes	FACU
2. *Daucus carota*	20	Yes	UPL
3. *Asclepias syriaca*	8	No	UPL
4. *Prunella vulgaris*	5	No	FAC
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	93	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	0	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	0	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	5	x 3 =	15
FACU species	60	x 4 =	240
UPL species	28	x 5 =	140
Column Totals	93	(A)	395 (B)
Prevalence Index = B/A =	4.2		

Hydrophytic Vegetation Indicators:

____ 1- Rapid Test for Hydrophytic Vegetation

____ 2 - Dominance Test is > 50%

____ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-08_UPL-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 14	10YR 4/3	100					Silt Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
___ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None
Depth (inches):

Hydric Soil Present? Yes ____ No ✓

Remarks:

Digging restriction due to shallow gravel.

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot East



Photo of Sample Plot South



WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: Flat Creek Solar Project **City/County:** Sprakers, Montgomery County **Sampling Date:** 2021-Sept-08
Applicant/Owner: SunEast **State:** NY **Sampling Point:** W-NSD-09_PEM-1
Investigator(s): Nick DeJohn, Brian Corrigan **Section, Township, Range:** NA
Landform (hillslope, terrace, etc.): Depression **Local relief (concave, convex, none):** Concave **Slope (%):** 0 to 1
Subregion (LRR or MLRA): LRR L **Lat:** 42.8646947863 **Long:** -74.486457361 **Datum:** WGS84
Soil Map Unit Name: Darien silt loam, 3 to 8 percent slopes **NWI classification:**
Are climatic/hydrologic conditions on the site typical for this time of year? Yes _✓_ No ____ (If no, explain in Remarks.)
Are Vegetation ____, Soil ____, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes _✓_ No ____
Are Vegetation ____, Soil ____, or Hydrology ____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes _✓_ No ____		
Hydric Soil Present?	Yes _✓_ No ____	**Is the Sampled Area within a Wetland?**	**Yes _✓_ No ____**
Wetland Hydrology Present?	Yes _✓_ No ____	**If yes, optional Wetland Site ID:**	W-NSD-09

Remarks: (Explain alternative procedures here or in a separate report)
Covertype is PEM.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one is required; check all that apply)

___ Surface Water (A1)
___ High Water Table (A2)
___ Saturation (A3)
___ Water Marks (B1)
___ Sediment Deposits (B2)
___ Drift Deposits (B3)
___ Algal Mat or Crust (B4)
___ Iron Deposits (B5)
___ Inundation Visible on Aerial Imagery (B7)
___ Sparsely Vegetated Concave Surface (B8)
___ Water-Stained Leaves (B9)
___ Aquatic Fauna (B13)
___ Marl Deposits (B15)
___ Hydrogen Sulfide Odor (C1)
___ Oxidized Rhizospheres on Living Roots (C3)
___ Presence of Reduced Iron (C4)
___ Recent Iron Reduction in Tilled Soils (C6)
___ Thin Muck Surface (C7)
___ Other (Explain in Remarks)

Secondary Indicators (minimum of two required)

___ Surface Soil Cracks (B6)
___ Drainage Patterns (B10)
___ Moss Trim Lines (B16)
___ Dry-Season Water Table (C2)
___ Crayfish Burrows (C8)
_✓_ Saturation Visible on Aerial Imagery (C9)
___ Stunted or Stressed Plants (D1)
_✓_ Geomorphic Position (D2)
___ Shallow Aquitard (D3)
___ Microtopographic Relief (D4)
_✓_ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present?	Yes ____ No _✓_	Depth (inches):	
Water Table Present?	Yes ____ No _✓_	Depth (inches):	**Wetland Hydrology Present?** Yes _✓_ No ____
Saturation Present? (includes capillary fringe)	Yes ____ No _✓_	Depth (inches):	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

VEGETATION -- Use scientific names of plants.

Sampling Point: W-NSD-09_PEM-1

Tree Stratum (Plot size: 30 ft)	Absolute % Cover	Dominant Species?	Indicator Status
1.			
2.			
3.			
4.			
5.			
6.			
7.			
	0	= Total Cover	
Sapling/Shrub Stratum (Plot size: 15 ft)			
1. *Salix alba*	10	Yes	FACW
2.			
3.			
4.			
5.			
6.			
7.			
	10	= Total Cover	
Herb Stratum (Plot size: 5 ft)			
1. *Phalaris arundinacea*	70	Yes	FACW
2. *Eupatorium perfoliatum*	15	No	FACW
3. *Scirpus cyperinus*	10	No	OBL
4. *Typha angustifolia*	10	No	OBL
5.			
6.			
7.			
8.			
9.			
10.			
11.			
12.			
	105	= Total Cover	
Woody Vine Stratum (Plot size: 30 ft)			
1.			
2.			
3.			
4.			
	0	= Total Cover	

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC:	2	(A)
Total Number of Dominant Species Across All Strata:	2	(B)
Percent of Dominant Species That Are OBL, FACW, or FAC:	100	(A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply By:	
OBL species	20	x 1 =	20
FACW species	95	x 2 =	190
FAC species	0	x 3 =	0
FACU species	0	x 4 =	0
UPL species	0	x 5 =	0
Column Totals	115	(A)	210 (B)

Prevalence Index = B/A = 1.8

Hydrophytic Vegetation Indicators:

✓ 1- Rapid Test for Hydrophytic Vegetation

✓ 2 - Dominance Test is >50%

✓ 3 - Prevalence Index is ≤ 3.0[1]

____ 4 - Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

____ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic

Definitions of Vegetation Strata:

Tree – Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

Sapling/shrub – Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall.

Herb – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

Woody vines – All woody vines greater than 3.28 ft in height.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks: (Include photo numbers here or on a separate sheet.)

SOIL

Sampling Point: W-NSD-09_PEM-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth	Matrix		Redox Features					
(inches)	Color (moist)	%	Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0 - 20	10YR 3/1	95	7.5YR 4/6	5	C	M	Clay Loam	

[1]Type: C = Concentration, D = Depletion, RM = Reduced Matrix, MS = Masked Sand Grains. [2]Location: PL = Pore Lining, M = Matrix.

Hydric Soil Indicators:

___ Histosol (A1)
___ Histic Epipedon (A2)
___ Black Histic (A3)
___ Hydrogen Sulfide (A4)
___ Stratified Layers (A5)
___ Depleted Below Dark Surface (A11)
___ Thick Dark Surface (A12)
___ Sandy Mucky Mineral (S1)
___ Sandy Gleyed Matrix (S4)
___ Sandy Redox (S5)
___ Stripped Matrix (S6)
___ Dark Surface (S7) **(LRR R, MLRA 149B)**
___ Polyvalue Below Surface (S8) **(LRR R, MLRA 149B)**
___ Thin Dark Surface (S9) **(LRR R, MLRA 149B)**
___ Loamy Mucky Mineral (F1) **(LRR K, L)**
___ Loamy Gleyed Matrix (F2)
___ Depleted Matrix (F3)
✓ Redox Dark Surface (F6)
___ Depleted Dark Surface (F7)
___ Redox Depressions (F8)

Indicators for Problematic Hydric Soils[3]:

___ 2 cm Muck (A10) **(LRR K, L, MLRA 149B)**
___ Coast Prairie Redox (A16) **(LRR K, L, R)**
___ 5 cm Mucky Peat or Peat (S3) **(LRR K, L, R)**
___ Dark Surface (S7) **(LRR K, L)**
___ Polyvalue Below Surface (S8) **(LRR K, L)**
___ Thin Dark Surface (S9) **(LRR K, L)**
___ Iron-Manganese Masses (F12) **(LRR K, L, R)**
___ Piedmont Floodplain Soils (F19) **(MLRA 149B)**
___ Mesic Spodic (TA6) **(MLRA 144A, 145, 149B)**
___ Red Parent Material (F21)
___ Very Shallow Dark Surface (TF12)
___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if observed):

Type: None

Depth (inches):

Hydric Soil Present? Yes ✓ No ____

Remarks:

Soil Photos



Photo of Sample Plot North



Photo of Sample Plot South